

<p>CORNER No. 25</p> <p>T21N RBE S22 S23 S27 S26 LS 4753 2002</p> <p>FD. A 3/4" IRON PIPE WITH ALUM. CAP LS 2670, 1959 IN A MOUND OF STONE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID PIPE ALONGSIDE. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE, 50' NORTHEAST OF A CREEK.</p> <p>FD. A 9" DOUGLAS FIR, S58°W, 5.0' -HB REC. A 5" DOUGLAS FIR, S55°W, 4.8' (1) FD. AN 18" DOUGLAS FIR, S58°E, 7.4' -HB REC. A 12" DOUGLAS FIR, S60°E, 7.5' (1) FD. A 30" DOUGLAS FIR, N13°W, 26.1' -HB REC. AN 11" WHITE FIR, N11°W, 25.3' (1) FD. A 36" INCENSE CEDAR, S78°E, 18.9' "X" IN BARK REC. A 30" INCENSE CEDAR, S70°E, 16.5' (1) FD. A 19" DOUGLAS FIR, S69°W, 9.2' "X" IN BARK REC. A 16" WHITE FIR, N68°E, 9.3' (1)</p>	<p>T21N RBE 1/4 S28 S27 LS 4753 2002</p> <p>CORNER No. 31</p> <p>FD. A 1" IRON PIPE IN A MOUND OF STONE (NO RECORD). SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID PIPE ALONGSIDE. CORNER FALLS ON A GENTLE SOUTHWEST SLOPE IN TIMBER.</p> <p>FD. A 18" INCENSE CEDAR, N38°E, 31.0' REC. A 10" CEDAR, N35°E, 47 LKS (GLO 1884) SCRIBED AN 18" INCENSE CEDAR, N82 1/2°E, 14.0' "1/4 S27 BT"</p>	<p><b>CORNER NOTES</b></p> <p>HB = HEALED BLAZE VS = VISIBLE SCRIBING (1) = REC. PER 2 R/S 81 (2) = REC. PER 7 R/S 140 (3) = REC. PER 5 RS 37 (4) = REC. PER 9 R/S 40</p>	<p>T20N 1/4 R7E R8E S1 S6 WC 2002</p> <p>CORNER No. 44</p> <p>FD. AN 18 X 10 X 8 INCH STONE MARKED "WC 1/4" IN A MOUND OF STONE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM. ROD AND REBUILT MOUND. CORNER FALLS ON A VERY STEEP SOUTHERLY SLOPE IN DENSE TAN OAK AND MAPLE, 35'± FROM THE CENTER OF A RAVINE.</p> <p>SCRIBED A 6" TAN OAK, S15°E, 14.6' "X BT" NO OTHER TREES AVAILABLE</p>	
<p>N 1/6 S29 S28 LS 4753 2002</p> <p>CORNER No. 26</p> <p>SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A STEEP NORTH SLOPE IN ROCKY SOIL AND SCATTERED TIMBER.</p> <p>SCRIBED A 6" PONDEROSA PINE, N70°W, 6.4' "N1/16 S28 BT"</p>	<p>T21N RBE S29 1/4 C S32 1987 LS 4753</p> <p>CORNER No. 32</p> <p>FD. A 3 1/4" U.S.F.S. ALUM. CAPPED MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A STEEP WEST SLOPE, 75'± FROM TOP OF BREAK.</p> <p>FD. A 40" LIVE OAK, N55°E, 17.8' REC. A 37" LIVE OAK, N65°E, 27 LKS (1) FD. A 13" BLACK OAK, S9°E, 21.1' REC. A 12" BLACK OAK, S9°E, 32 LKS (1)</p>	<p>T21N S1 S6 R7E R8E CC T20N LS 4753 2002</p> <p>CORNER No. 38</p> <p>FD. ORIG. STONE IN A MOUND OF STONE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM. ROD IN A MOUND OF STONE AT TRUE INTERSECTION, 6'± NORTH OF ORIG. STONE. CORNER FALLS IN A ROCKY HIGH WATER RIVER BED, 40'± EAST OF EAST EDGE OF WATER AS OF 6-19-02.</p> <p>SCRIBED A 17" DOUGLAS FIR, S31°E, 12.5' "T20N RBE S6 CC BT"</p>	<p>T21N R7E S36 S31 S1 T20N R7E 1978</p> <p>CORNER No. 75</p> <p>FD. A 3 1/4" U.S.F.S. ALUM. CAPPED MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A STEEP SOUTH SLOPE IN TIMBER AND HEAVY TAN OAK.</p> <p>FD. A 49" WHITE FIR N31°E, 38.9' REC. A 47" DOUGLAS FIR, N31°E, 59 LKS (1) FD. A 18" SUGAR PINE, N52°E, 19.5' -HB REC. A 13" SUGAR PINE, N52°E, 29 1/2 LKS (1) FD. A 20" PINE SNAG, N86°W, 29.4' -HB REC. A 22" YELLOW PINE, N86°W, 44 1/2 LKS (1) FD. A 49" WHITE FIR S86°E, 20.5' -HB REC. A 47" DOUGLAS FIR, S86°E, 31 LKS (1)</p>	
<p>N 1/6 S29 S28 LS 4753 2002</p> <p>CORNER No. 27</p> <p>SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTH SLOPE IN TIMBER, 50'± WEST OF A RAVINE.</p> <p>SCRIBED AN 8" WHITE FIR, N1°W, 21.3' "CN 1/16 S28 BT" SCRIBED A 6" WHITE FIR, N83°E, 20.9' "CN 1/16 S28 BT"</p>	<p>T21N RBE S28 1/4 C S33 LS 4753 2002</p> <p>CORNER No. 34</p> <p>FD. A 22 X 15 X 5 INCH (REC. 18 X 12 X 5 INCH) STONE - NO MARKS - IN A MOUND OF STONE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD AND REBUILT MOUND. CORNER FALLS ON A STEEP EAST SLOPE, 150'± WEST OF A CREEK IN TIMBER AND BRUSH.</p> <p>FD. A 48" INCENSE CEDAR, S26°E, 16.5' -HB REC. A 27" CEDAR, S16°E, 25 LKS (GLO 1884) FD. A 40" DOUGLAS FIR WITH A ROTTING BOLE, N34 1/2°E, 19.4' REC. A 6" FIR, N39°E, 29 LKS (GLO 1884) SCRIBED A 10" DOUGLAS FIR, N73°W, 11.8' "1/4 S28 BT"</p>	<p>T21N 1/4 S6 T20N RBE LS 4753 2002</p> <p>CORNER No. 39</p> <p>SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM. ROD. CORNER FALLS ON A STEEP NORTHERLY SLOPE IN SMALL TO MID-SIZE TIMBER AND DENSE UNDERBRUSH.</p> <p>SCRIBED A 9" INCENSE CEDAR, S89°E, 20.2' "1/4 S6 BT"</p>	<p>T21N RBE SC S31 1/4 COR LS 3625 1978</p> <p>CORNER No. 76</p> <p>FD. A 3 1/4" U.S.F.S. ALUM. CAPPED MONUMENT IN A MOUND OF STONE WITH ORIGINAL STONE ALONGSIDE MARKED "1/4 CC". CORNER FALLS ON A MODERATE NORTHWEST SLOPE IN LARGE TIMBER AND THICK TAN OAK.</p> <p>FD. A 47" DOUGLAS FIR, S81°W, 16.3' -HB REC. A 42" DOUGLAS FIR, S78°W, 24 LKS (1) FD. A 64" DOUGLAS FIR, N2°E, 22.6' -HB REC. A 56" DOUGLAS FIR, N2°E, 32 LKS (1)</p>	
<p>N 1/6 S28 S27 LS 4753 2002</p> <p>CORNER No. 28</p> <p>SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A TIMBERED FLAT AT THE SOUTHWEST CORNER OF A TREE PLANTATION.</p> <p>SCRIBED A 16" WHITE FIR, N56°W, 8.4' "N1/16 S28 BT" SCRIBED A 20" WHITE FIR, N15 1/4°E, 48.2' "N1/16 S28 BT"</p>	<p>T21N RBE 1/4 C S31 S32 LS 3625 1978</p> <p>CORNER No. 35</p> <p>FD. A 3 1/2" U.S.F.S. ALUM. CAPPED MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A STEEP EAST SLOPE.</p> <p>FD. A 34" WHITE FIR, N8°E, 29.0' -HB REC. A 22" WHITE FIR, N8°E, 44 LKS (1) FD. A 44" DOUGLAS FIR, S50°W, 23.8' -HB REC. A 36" DOUGLAS FIR, S50°W, 36 LKS (1)</p>	<p>T21N RBE SC S31 S32 S6 T20N LS 1978</p> <p>CORNER No. 40</p> <p>FD. A 3 1/2" U.S.F.S. ALUM. CAPPED MONUMENT IN A MOUND OF STONE. CORNER FALLS IN A FLAT, OPEN TIMBERED AREA, 80'± WEST OF A DIRT ROAD.</p> <p>FD. A 28" SUGAR PINE, N55°E, 18.0' -HB REC. A 21" SUGAR PINE, N55°E, 27 1/2 LKS (1) FD. A 18" INCENSE CEDAR, N19°W, 24.8' -HB REC. A 14" INCENSE CEDAR, N19°W, 37 1/2 LKS (1)</p>	<p>RM 12.0' TO LINE TREE LS 4753 2002</p> <p>CORNER No. 78</p> <p>FD. A 61" INCENSE CEDAR (REC. 30" CEDAR - KEDDIE, 1869) LINE TREE WITH HACKS VISIBLE ON THE EAST SIDE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM. ROD N69°W, 12.0' FROM TREE</p>	<p>CORNER No. 77</p> <p>FD. A 24" BLACK OAK (REC. 14" - HALL, 1884) LINE TREE WITH HACKS VISIBLE ON THE SOUTH SIDE.</p>
<p>T21N RBE 1/4 COR S29 S28 LS 4208 1987</p> <p>CORNER No. 29</p> <p>FD. A 3 1/4" U.S.F.S. ALUM. CAPPED MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A SLIGHT SOUTH SLOPE. A 1 1/2" IRON PIPE (NO ID) BEARS N70°E, 4.25'.</p> <p>FD. A 69" SUGAR PINE, N70°E, 23.8' -VS REC. A 70" SUGAR PINE, N70°E, 36 LKS (1) FD. A 26" DOUGLAS FIR, N59°W, 20.5' -HB REC. A 12" DOUGLAS FIR, N59°W, 31 LKS (1) FD. AN 18" INCENSE CEDAR, S10°W, 15.2' "X" IN BARK REC. AN 18" INCENSE CEDAR, S7°E, 21-1/2 LKS (1) FD. A 22" BLACK OAK, N2°W, 19.8' "X" IN BARK REC. A 22" BLACK OAK, N10°E, 32 LKS (1)</p>	<p>T21N RBE C 1/4 S32 LS 4753 2002</p> <p>CORNER No. 36</p> <p>SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD IN A MOUND OF STONE. CORNER FALLS IN A MINED AREA IN TIMBER.</p> <p>SCRIBED A 10" DOUGLAS FIR, N79 3/4°E, 37.9' "C1/4 S32 BT" SCRIBED A 7" DOUGLAS FIR, S0 1/4°W, 11.2' "C1/4 S32 BT"</p>	<p>T21N RBE CC S6 S5 T20N LS 3966 1990</p> <p>CORNER No. 41</p> <p>FD. A 3 1/2" U.S.F.S. ALUM. CAPPED MONUMENT IN A MOUND OF STONE. CORNER FALLS AT THE NORTHWEST CORNER OF A LOGGED CLEARING ON FLAT GROUND.</p> <p>FD. A 15" DOUGLAS FIR, S47°W, 32.8' REC. A 12" DOUGLAS FIR, S47°W, 32.8' (1)</p>	<p>RM 12.6' TO LINE TREE LS 4753 2002</p> <p>CORNER No. 79</p> <p>FD. A 41" CEDAR LINE TREE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM. ROD N46°W, 12.6' FROM TREE</p>	
<p>RM T21N RBE C 1/4 S28 LS 4753 2002</p> <p>CORNER No. 30</p> <p>CORNER FALLS ON A GENTLE SOUTH SLOPE AT THE EDGE OF A NEW LOGGING ROAD, 0.5' INTO THE EAST SIDE OF 46" SUGAR PINE SCRIBED "C 1/4 S28" ON THE EAST SIDE.</p> <p>SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD FOR R.M. IN 1" IRON PIPE IN A MOUND OF STONE. R.M. BEARS S 56°46' W, 7.8' FROM CORNER.</p>	<p>T21N RBE 1/4 S32 S33 LS 4753 2002</p> <p>CORNER No. 37</p> <p>FD. A 1 1/4" IRON PIPE IN A MOUND OF STONE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM ROD, REBUILT MOUND AND LAID PIPE ALONGSIDE. CORNER FALLS ON A GENTLE SOUTHEAST SLOPE AT THE EDGE OF A TREE PLANTATION.</p> <p>SCRIBED AN 8" PONDEROSA PINE, N39°W, 32.6' "1/4 S32 BT" SCRIBED AN 11" PONDEROSA PINE, N50°E, 43.0' "1/4 S32 BT" FD. A TAG ON AN 8" CEDAR WHICH READS: "SCRIBING FD. INSIDE ORIG. BO LYING ON GROUND BEARS S50°W (BASE OF TREE BEARS S89°W FROM CORNER)"</p>	<p>T21N RBE 1/4 S32 T20N RBE LS 3966 1990</p> <p>CORNER No. 42</p> <p>FD. A 3 1/2" U.S.F.S. ALUM. CAPPED MONUMENT IN A MOUND OF STONE. CORNER FALLS ON SLIGHT EAST SLOPE ON THE NORTH EDGE OF A LOGGED CLEARING.</p> <p>FD. A 12" INCENSE CEDAR, N36°W, 6.2' REC. A 10" CEDAR, N36°W, 6.2' (1) FD. A 20" BLACK OAK SNAG, N10 1/2°W, 16.5' REC. A 21" BLACK OAK, N73°30'W, 16.5' (1)</p>	<p>RM 11.9' TO LINE TREE LS 4753 2002</p> <p>CORNER No. 80</p> <p>FD. A 54" DOUGLAS FIR LINE TREE WITH HACKS VISIBLE ON THE EAST SIDE. SET A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM. ROD N52°E, 11.9' FROM TREE</p>	
			<p>T20N RBE RM 12.5' LS 3966 1990</p> <p>CORNER No. 99</p> <p>FD. A 30" CEDAR WITH HACKS ON EAST AND WEST SIDES FROM WHICH A 3 1/4" U.S.F.S. ALUM. CAP ON A 5/8" ALUM. ROD SET FOR R.M. PER (1)4 BEARS N86°25'W, 17.0'.</p>	

**RECORD OF SURVEY**

FOR

**USDA FOREST SERVICE**

**PLUMAS NATIONAL FOREST**

"SOUTH FORK CADASTRAL"

IN SECTIONS 14, 22, 28, 31 AND 32,  
T. 21 N., R. 8 E., M.D.M.  
IN THE UNINCORPORATED AREA  
OF PLUMAS COUNTY,  
STATE OF CALIFORNIA

**DEL TERRA INC.**  
**SURVEYING**  
1168 INDUSTRIAL ST.  
REDDING, CA 96002  
PHONE (530) 241-8050

DATE: JULY, 2002  
SHEET 4 OF 4