


<p>T30N R7E 1/4 S11 S14 LS 4753 2003</p> <p>CORNER No. 2 FD. A 15 X 12 X 9 INCH (16 X 14 X 12) STONE MARKED "1/4" IN A MOUND OF STONE. SET STD USFS MONUMENT, REBUILT MOUND AND LAID MARKED STONE ALONGSIDE. CORNER FALLS ON A GENTLE NORTHEAST SLOPE IN SCATTERED BRUSH AND TIMBER, 300'± SOUTH OF A LAVA RIM.</p> <p>SCRIBED A 15" TAMARACK, N5°W, 61.1' "1/4 S11 BT" SCRIBED AN 8" RED FIR, S72°W, 22.3' "1/4 S14 BT" FD. FIR REMAINS, S48°E, 80'± REC. A 24" WHITE FIR, S48°E, 112 LKS (1)</p>	<p>T30N R7E 1/4 S19 S30 LS 4753 2003</p> <p>CORNER No. 10</p> <p>SET STD USFS MONUMENT IN A MOUND OF STONE. CORNER FALLS IN A FLAT AREA IN TIMBER OF TAMARACK, RED FIR AND WHITE FIR.</p> <p>FD. AN 18" TAMARACK STUMP, S10°E, 11.9' -VS REC. AN 11" LARCH, S10°E, 18 LKS (1) FD. A 38" FIR, N14°E, 25.6' -HB REC. A 7" WHITE FIR, N8°W, 47 LKS (1) SCRIBED A 15" TAMARACK, S13 1/2°E, 28.9' "T30N R7E S30 BT" SCRIBED AN 8" TAMARACK, N39 1/2°E, 7.0' "T30N R7E S19 BT"</p>	<p>CORNER NOTES</p> <p>CW = CARIBOU WILDERNESS HB = HEALED BLAZE VS = VISIBLE SCRIBING BCIP = BRASS CAPPED IRON PIPE STD. USFS MON. = 3 1/2" ALUM CAP ON A 2 1/2" ALUM PIPE. (1) = REC. PER GLO</p>	<p>RM 4.3' TO COR NE 1/16 S30 LS 4753 2003</p> <p>CORNER No. 19</p> <p>CORNER FALLS IN THE NORTHWEST SIDE OF A 12" WHITE FIR. SET 20D NAIL IN NOTCH AND SCRIBED TREE "NE 1/16 S30" ABOVE NOTCH. SET STD USFS MONUMENT FOR RM FROM WHICH THE CORNER BEARS S52°E, 4.25'. CORNER FALLS ON A MODERATE WEST SLOPE IN TIMBER, 100' EAST OF A STEEP DROP.</p> <p>SCRIBED A 14" WHITE FIR, S50°W, 11.9' "NE 1/16 S30 BT"</p>	<p>T30N 1/4 R6E R7E S25 S30 LS 4753 2003</p> <p>CORNER No. 26</p> <p>FD. A 16 X 9 X 7 INCH (26 X 7 X 6) STONE MARKED "1/4" ON THE WEST FACE PER (1). SET STD USFS MONUMENT AND REBUILT MOUND WITH MARKED STONE AT BASE.</p> <p>FD. A 40" FIR STUMP, S85°E, 36.7' REC. A 36" WHITE FIR, S85°E, 55 LKS (1) FD. A 40" WHITE FIR, N55°W, 37.0' -HB REC. A 24" WHITE FIR, N55°W, 56 LKS (1) SCRIBED A 22" RED FIR, S57°E, 37.2' "1/4 S30 BT"</p>
<p>T30N R7E S11 S12 S14 S13 LS 4753 2003</p> <p>CORNER No. 3</p> <p>FD. A 16 X 10 X 6 INCH STONE WITH 4 NOTCHES SOUTH AND 1 NOTCH EAST IN A MOUND OF STONE PER (1). SET STD USFS MONUMENT, REBUILT MOUND AND LAID MARKED STONE ALONGSIDE. CORNER FALLS ON A FLAT IN SCATTERED FIR AND THICK BRUSH.</p> <p>SCRIBED AN 11" TAMARACK, S56°W, 10.8' "T30N R7E S14 BT" SCRIBED AN 11" TAMARACK, N36°W, 20.4' "T30N R7E S11 BT" SCRIBED AN 11" TAMARACK, S62°E, 6.8' "T30N R7E S13 BT" SCRIBED A 9" WHITE FIR, N65°E, 16.7' "T30N R7E S12 BT"</p>	<p>T30N R7E S19 S20 S30 S29 LS 4753 2003</p> <p>CORNER No. 11</p> <p>FD. A 22 X 7 X 5 INCH STONE WITH 5 NOTCHES EAST AND 2 NOTCHES SOUTH PER (1). SET STD USFS MONUMENT, REBUILT MOUND AND LAID MARKED STONE ALONGSIDE. CORNER FALLS IN A FLAT AREA IN SCATTERED FIR AND CHAPARRAL.</p> <p>FD. A 21" WHITE FIR, N54°E, 28.0' -HB REC. A 4" WHITE FIR, N54°E, 43 LKS (1) FD. A 37" WHITE FIR, N4°W, 23.6' -HB REC. A 9" WHITE FIR, N7°W, 36 LKS (1) FD. A 20" WHITE FIR, S79°W, 16.0' -HB REC. A 7" WHITE FIR, S81°W, 23 LKS (1) FD. A WHITE FIR STUMP, S52°E, 38.5' REC. A 28" WHITE FIR, S52°E, 52 LKS (1)</p>	<p>T30N R7E S21 S22 S28 S27 LS 4753 2003</p> <p>CORNER No. 15</p> <p>FD. AN 18 X 16 X 11 INCH (18 X 10 X 8) WITH 2 NOTCHES SOUTH AND 3 NOTCHES EAST IN A MOUND OF STONE. SET STD USFS MONUMENT, REBUILT MOUND AND LAID MARKED STONE ALONGSIDE. CORNER FALLS IN A TIMBERED FLAT, 35'± SOUTH OF A STREAM.</p> <p>FD. A 40" WHITE FIR, S50°W, 43.4' -HB REC. A 22" RED FIR, S52°W, 65 LKS (1) FD. A 38" WHITE FIR, S81°E, 34.5' -HB REC. A 10" WHITE FIR, S60°E, 52 LKS (1) FD. A DEAD AND DOWN TAMARACK, N80°E, 32.3' -VS REC. A 10" LARCH, N80°E, 49 LKS (1) FD. A FIR STUMP, N38°W, 7.8' REC. A 26" RED FIR, N38°W, 12 LKS (1)</p>	<p>N 1/16 S30 S29 LS 4753 2003</p> <p>CORNER No. 20</p> <p>SET STD USFS MONUMENT IN A SMALL MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE IN RED FIR TIMBER, 120'± EAST OF A LOW SWALE.</p> <p>SCRIBED AN 8" RED FIR, S30°E, 38.5' "N 1/16 S29 BT" SCRIBED AN 8" RED FIR, N16°W, 18.7' "N 1/16 S30 BT"</p>	<p>E 1/16 C—C S30 LS 4753 2003</p> <p>CORNER No. 27</p> <p>SET STD USFS MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A MODERATE WEST SLOPE AT THE EDGE OF A BREAK.</p> <p>SCRIBED A 10" WHITE FIR, N27°W, 9.2' "CE 1/16 S30 BT" SCRIBED A 10" WHITE FIR, N80°W, 6.4' "CE 1/16 S30 BT"</p>
<p>CW S12 S13 LS 4753 2003</p> <p>CORNER No. 4</p> <p>SET STD USFS MONUMENT IN A MOUND OF STONE. CORNER FALLS IN A LOW AREA, 10' NORTH OF A CREEK AND 6' WEST OF A TRAIL.</p> <p>SCRIBED A 15" TAMARACK, N28 1/2°E, 17.3' "X BT" SCRIBED A 14" TAMARACK, N21 1/2°W, 24.0' "X BT"</p>	<p>T30N R7E 1/4 S20 S29 LS 4753 2003</p> <p>CORNER No. 12</p> <p>NO ORIGINAL EVIDENCE FOUND. AT PORPORTIONED POSITION, SET STD USFS MONUMENT IN A MOUND OF STONE AT PROPORTIONED POSITION. CORNER FALLS ON A STEEP EAST SLOPE IN HEAVY TIMBER.</p> <p>SCRIBED A 9" WHITE FIR, S74°E, 15.8' "1/4 S29 BT" SCRIBED A 15" RED FIR, N49°W, 40.0' "1/4 S20 BT"</p>	<p>T30N R7E 1/4 S22 S27 LS 4753 2003</p> <p>CORNER No. 16</p> <p>FD. AN 18 X 13 X 8 INCH (20 X 14 X 5) STONE MARKED "1/4" ON NORTH FACE. SET STD USFS MONUMENT, REBUILT MOUND AND LAID MARKED STONE ALONGSIDE. CORNER FALLS IN A TIMBERED FLAT, 75'± SOUTHEAST OF A DRAINAGE.</p> <p>FD. A DEAD AND DOWN TAMARACK, S48°W, 12.0' -VS REC. A 5" LARCH, S48°W, 18 LKS (1) SCRIBED AN 8" TAMARACK, N10°E, 22.0' "1/4 S22 BT" SCRIBED AN 8" TAMARACK, S89°E, 9.0' "1/4 S27 BT"</p>	<p>N 1/16 C S29 LS 4753 2003</p> <p>CORNER No. 21</p> <p>SET STD USFS MONUMENT. NO MOUND. CORNER FALLS ON A MODERATE EAST SLOPE, 4' FROM A LARGE SNAG.</p> <p>SCRIBED A 13" WHITE FIR, N84°W, 17.4' "CN 1/16 S29 BT" SCRIBED A 13" WHITE FIR, S7°E, 30.0' "CN 1/16 S29 BT"</p>	<p>T30N R7E 1/4 S30 S29 LS 4753 2003</p> <p>CORNER No. 28</p> <p>FD. A LARGE, ROTTED RED FIR STUMP. SET STD USFS MONUMENT IN A MOUND OF STONE IN REMAINS OF STUMP. CORNER FALLS IN A FLAT, LOGGED AREA AT THE NORTH EDGE OF A CLEAR CUT.</p> <p>FD. A 36" RED FIR STUMP WITH PARTIAL FACE, CHAINING NOTCH AND VS, S32°E, 34.1' REC. A 26" RED FIR, S32°E, 52 LKS (1) SCRIBED A 28" TAMARACK, N16 3/4°W, 97.4' "1/4 S30 BT" SCRIBED A 6" WHITE FIR, N58 1/4°E, 11.1' "X BT"</p>
<p>T30N R7E 1/4 S12 S13 LS 4753 2003</p> <p>CORNER No. 5</p> <p>SET STD USFS MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A GENTLE EAST SLOPING SPUR.</p> <p>FD. FIR REMAINS AND STUMP HOLE, S10°E, 14.5' REC. A WHITE FIR, S10°E, 22 LKS (1) SCRIBED A 5" RED FIR, S21°E, 9.6' "X BT" SCRIBED A 14" WHITE FIR, N51°W, 28.1' "1/4 S12 BT"</p>	<p>T30N R7E S20 S21 S29 S28 LS 4753 2003</p> <p>CORNER No. 13</p> <p>FD. A 18 X 16 X 7 INCH (18 X 12 X 6) STONE WITH 2 NOTCHES SOUTH AND 3 NOTCHES EAST. SET STD USFS MONUMENT, REBUILT MOUND WITH MARKED STONE AT BASE. CORNER FALLS ON AN OPEN, MODERATE EAST SLOPE, 100'± EAST OF THE TOP OF A SPUR.</p> <p>FD. A 34" WHITE FIR, S16°W, 62.1' -HB REC. A 7" WHITE FIR, S16°W, 94 LKS (1) FD. A ROTTED FIR SNAG, N75°W, 56'± REC. A 12" WHITE FIR, N75°W, 85 LKS (1) SCRIBED A 12" TAMARACK, S48°E, 52.5' "T30N R7E S28 BT" SCRIBED A 14" WHITE FIR, N67°E, 45.4' "T30N R7E S21 BT"</p>	<p>T30N R7E S22 S23 S27 S26 LS 4753 2003</p> <p>CORNER No. 17</p> <p>FD. A 20 X 8 X 6 INCH (20 X 7 X 5) WITH 2 NOTCHES SOUTH AND EAST. SET STD USFS MONUMENT, REBUILT MOUND AND LAID MARKED STONE ALONGSIDE. CORNER FALLS ON A FLAT IN SCATTERED TIMBER AT THE EAST OF A SMALL, 8' HIGH LAVA REEF.</p> <p>FD. A TAMARACK SNAG, S80°E, 13.6' -VS REC. A 12" LARCH, S40°E, 18 LKS (1) FD. A 25" TAMARACK, N10°W, 40.9' -VS REC. A 14" LARCH, N10°W, 60 LKS (1) SCRIBED A 21" TAMARACK, N68°E, 38.2' "T30N R7E S23 BT" SCRIBED A 17" TAMARACK, S70°E, 9.0' "T30N R7E S26 BT"</p>	<p>N 1/16 S29 S28 LS 4753 2003</p> <p>CORNER No. 22</p> <p>SET STD USFS MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A GENTLE SOUTH SLOPE IN TIMBER, 250'± NORTH OF ROAD 30N72.</p> <p>SCRIBED A 10" RED FIR, N35°W, 12.2' "N 1/16 S29 BT" SCRIBED A 19" TAMARACK, S75 1/2°E, 16.8' "N 1/16 S28 BT"</p>	<p>T30N R7E 1/4 S29 S28 LS 4753 2003</p> <p>CORNER No. 29</p> <p>FD. A 19 X 14 X 6 INCH (16 X 10 X 7) MARKED STONE IN A SMALL MOUND. SET STD USFS MONUMENT AND REBUILT MOUND WITH MARKED STONE AT BASE. CORNER FALLS ON A LOGGED FLAT IN SCATTERED RED FIR, 20'± SOUTH OF A ROAD.</p> <p>FD. A TAMARACK STUMP, S70°W, 21.0' REC. 24" LARCH, S75°W, 35 LKS (1) SCRIBED A 10" TAMARACK, S22°E, 27.9' "1/4 S28 BT" SCRIBED A 10" TAMARACK, S48°W, 25.2' "1/4 S29 BT"</p>
<p>T30N R7E 1/4 S14 S23 LS 4753 2003</p> <p>CORNER No. 7</p> <p>FD. A 20 X 14 X 7 INCH (18 X 12 X 6) IN A MOUND OF STONE. SET STD USFS MONUMENT, REBUILT MOUND WITH STONE AT BASE. CORNER FALLS ON A GENTLE SOUTH SLOPE IN SCATTERED TIMBER.</p> <p>FD. A 37" PONDEROSA PINE, S25°E, 21.1' -HB REC. A 22" PITCH PINE, S10°E, 32 LKS (1) FD. A DOWN TAMARACK, N33°E, 51.5' -VS REC. A 7" LARCH, N33°E, 78 LKS (1) SCRIBED A 14" JEFFREY PINE, N36°E, 63.7' "1/4 S14 BT"</p>	<p>T30N R7E 1/4 S21 S28 LS 4753 2003</p> <p>CORNER No. 14</p> <p>FD. AN 18 X 14 X 12 INCH (18 X 10 X 8) STONE MARKED "1/4" ON NORTH FACE. SET STD USFS MONUMENT, REBUILT MOUND AND LAID MARKED STONE ALONGSIDE. CORNER FALLS ON THE NORTHEAST SIDE OF AN EAST WEST LAVA REEF IN SCATTERED TIMBER.</p> <p>FD. A 35" RED FIR, S39°E, 23.2' -HB REC. A 9" WHITE FIR, S39°E, 35 LKS (1) FD. A 21" TAMARACK, N9°E, 46.2' -HB REC. A 10" LARCH, N9°E, 70 LKS (1)</p>	<p>T30N R7E 1/4 S23 S26 LS 4753 2003</p> <p>CORNER No. 18</p> <p>FD. A 21 X 14 X 10 INCH (18 X 8 X 6) MARKED STONE IN A SMALL MOUND OF STONE. SET STD USFS MONUMENT AND REBUILT MOUND WITH MARKED STONE AT BASE. CORNER FALLS ON A GENTLE SOUTHEAST SLOPE IN SCATTERED TIMBER.</p> <p>SCRIBED AN 11" WHITE FIR, N27°W, 11.3' "1/4 S23 BT" SCRIBED A 13" WHITE FIR, S56°E, 46.3' "1/4 S26 BT"</p>	<p>N 1/16 C S28 LS 4753 2003</p> <p>CORNER No. 23</p> <p>SET STD USFS MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTH SLOPE IN SCATTERED TIMBER.</p> <p>SCRIBED A 9" TAMARACK, S34°W, 34.5' "CN 1/16 S28 BT" SCRIBED A 17" JEFFREY PINE, S73°E, 27.8' "CN 1/16 S28 BT"</p>	<p>RECORD OF SURVEY</p> <p>FOR</p> <p>USDA FOREST SERVICE PLUMAS NATIONAL FOREST</p> <p>"SOUTH CARIBOU"</p> <p>IN SECTIONS 13, 14 & 23 IN THE UNINCORPORATED AREA OF LASSEN COUNTY, AND IN SECTIONS 23, 27, 28, 29 AND 30 IN THE UNINCORPORATED AREA OF PLUMAS COUNTY, ALL IN T 30 N, R 7 E, MDM, STATE OF CALIFORNIA</p> <div data-bbox="2368 1793 2763 1927">  <p>DEL TERRA INC. SURVEYING 1168 INDUSTRIAL ST. REDDING, CA 96002 PHONE (530) 241-8050</p> </div> <p>DATE: NOVEMBER, 2003 SHEET 3 OF 4</p>
<p>T30N R7E 1/4 S11 S14 LS 4753 2003</p> <p>CORNER No. 2</p> <p>FD. A 15 X 12 X 9 INCH (16 X 14 X 12) STONE MARKED "1/4" IN A MOUND OF STONE. SET STD USFS MONUMENT, REBUILT MOUND AND LAID MARKED STONE ALONGSIDE. CORNER FALLS ON A GENTLE NORTHEAST SLOPE IN SCATTERED BRUSH AND TIMBER, 300'± SOUTH OF A LAVA RIM.</p> <p>SCRIBED A 15" TAMARACK, N5°W, 61.1' "1/4 S11 BT" SCRIBED AN 8" RED FIR, S72°W, 22.3' "1/4 S14 BT" FD. FIR REMAINS, S48°E, 80'± REC. A 24" WHITE FIR, S48°E, 112 LKS (1)</p>	<p>T30N R7E 1/4 S19 S30 LS 4753 2003</p> <p>CORNER No. 10</p> <p>SET STD USFS MONUMENT IN A MOUND OF STONE. CORNER FALLS IN A FLAT AREA IN TIMBER OF TAMARACK, RED FIR AND WHITE FIR.</p> <p>FD. AN 18" TAMARACK STUMP, S10°E, 11.9' -VS REC. AN 11" LARCH, S10°E, 18 LKS (1) FD. A 38" FIR, N14°E, 25.6' -HB REC. A 7" WHITE FIR, N8°W, 47 LKS (1) SCRIBED A 15" TAMARACK, S13 1/2°E, 28.9' "T30N R7E S30 BT" SCRIBED AN 8" TAMARACK, N39 1/2°E, 7.0' "T30N R7E S19 BT"</p>	<p>T30N R7E 1/4 S22 S27 LS 4753 2003</p> <p>CORNER No. 16</p> <p>FD. AN 18 X 13 X 8 INCH (20 X 14 X 5) STONE MARKED "1/4" ON NORTH FACE. SET STD USFS MONUMENT, REBUILT MOUND AND LAID MARKED STONE ALONGSIDE. CORNER FALLS IN A TIMBERED FLAT, 75'± SOUTHEAST OF A DRAINAGE.</p> <p>FD. A DEAD AND DOWN TAMARACK, S48°W, 12.0' -VS REC. A 5" LARCH, S48°W, 18 LKS (1) SCRIBED AN 8" TAMARACK, N10°E, 22.0' "1/4 S22 BT" SCRIBED AN 8" TAMARACK, S89°E, 9.0' "1/4 S27 BT"</p>	<p>N 1/16 S29 S28 LS 4753 2003</p> <p>CORNER No. 22</p> <p>SET STD USFS MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A GENTLE SOUTH SLOPE IN TIMBER, 250'± NORTH OF ROAD 30N72.</p> <p>SCRIBED A 10" RED FIR, N35°W, 12.2' "N 1/16 S29 BT" SCRIBED A 19" TAMARACK, S75 1/2°E, 16.8' "N 1/16 S28 BT"</p>	<p>T30N R7E 1/4 S29 S28 LS 4753 2003</p> <p>CORNER No. 29</p> <p>FD. A 19 X 14 X 6 INCH (16 X 10 X 7) MARKED STONE IN A SMALL MOUND. SET STD USFS MONUMENT AND REBUILT MOUND WITH MARKED STONE AT BASE. CORNER FALLS ON A LOGGED FLAT IN SCATTERED RED FIR, 20'± SOUTH OF A ROAD.</p> <p>FD. A TAMARACK STUMP, S70°W, 21.0' REC. 24" LARCH, S75°W, 35 LKS (1) SCRIBED A 10" TAMARACK, S22°E, 27.9' "1/4 S28 BT" SCRIBED A 10" TAMARACK, S48°W, 25.2' "1/4 S29 BT"</p>