

SECTION 27 & 28

① **W 1/16 S21/S28**
 RECORD: NONE
 FOUND: STARDARD USFS MONUMENT IN MOS LS5623 (SEE NOTE)
 FWB: 14" FIR S81°59'W 13.0' SCRIBED "W 1/16 S28 BT"
 FWB: 11" FIR S23°09'E 19.4' SCRIBED "W 1/16 S28 BT"
 SET: NOTHING - ACCEPTED USFS CORNER

② **N 1/4 S28**
 RECORD: SET POST (R1)
 FWB: 12" SUGAR PINE N46°W 7 LKS SCRIBED " 1/4 S28 BT" (R1)
 FWB: 10" SUGAR PINE S10°E 9 LKS SCRIBED " 1/4 S28 BT" (R1)
 FOUND: STANDARD USFS MONUMENT IN MOS LS5623 (SEE NOTE)
 FWB: 14" FIR S1°57'W 9.5' SCRIBED "1/4 S28 BT"
 FWB: 11" FIR S30°13'W 1.3' SCRIBED "1/4 S28 BT"
 SET: NOTHING - ACCEPTED USFS CORNER

③ **E 1/16 S21/S28**
 RECORD: NONE
 FOUND: STANDARD USFS MONUMENT IN MOS LS5623 (SEE NOTE)
 FWB: 11" FIR N68°18'E 9.8' SCRIBED "E 1/16 S21 BT"
 FWB: 10" CEDAR S67°56"W 7.2' SCRIBED "E 1/16 S28 BT"
 SET: NOTHING - ACCEPTED USFS CORNER

④ **NE CORNER SECTION 28**
 RECORD: GLO SET POST (R1)
 FWB: 10" CEDAR N30°E 27 LKS. (R1)
 FWB: 36" FIR N30°E 35 LKS. (R1)
 FWB: 10" FIR S50°E 60 LKS (R1)
 FWB: 10" BLACK OAK N60°W 162 LKS (R1)
 FOUND: 3 1/4" ALM CAP ON 2 1/2" ALM PIPE RCE 19119 (R2)
 FWB: 37" CEDAR S20°04'W 17.9 SCRIBING VISIBLE (R2)
 FWB: 22" FIR SNAG S40°12'E 39.9' SCRIBING VISIBLE. (R2)
 SET: NOTHING - ACCEPTED EXISTING CORNER

⑤ **NE CORNER SECTION 15**
 RECORD: GLO SET POST (R1)
 FWB: 36" SUGAR PINE S85°W 90 LKS (R1)
 FWB: 20" FIR N82°E 103 LKS (R1)
 FWB: 7" FIR S5°E 262 LKS (R1)
 FOUND: STANDARD USFS MONUMENT IN MOS LS5623 (SEE NOTE)
 FWB: 40" SUGAR PINE S80°W 90 LKS SCRIBING VISIBLE (R1)
 FWB: 41" FIR S5°E 262 LKS (R1)
 SET: NOTHING - ACCEPTED EXIST USFS CORNER

⑥ **NE CORNER SECTION 25**
 RECORD: GLO CEDAR POST 4"x4"x4' LONG (R1)
 FWB: 18" FIR N34°E 117 LKS (R1)
 FWB: 50" FIR N88°W 25 LKS (R1)
 FWB: 24" FIR S63°E 35 LKS (R1)
 FOUND: 1/2" REBAR MKD LS2932 IN MOS (NO RECORD FD.)
 FWB: 64" FIR S80°W 25 LKS SCRIBING VISIBLE (R1)
 SET: NOTHING - ACCEPTED EXIST CORNER

⑦ **CN1/16 SECTION 28**
 RECORD: NONE
 FOUND: STANDARD USFS MONUMENT IN MOS LS5623 (SEE NOTE)
 FWB: 23" FIR N12°33'E 19.5' SCRIBED "CN 1/16 S28 BT"
 FWB: 25" FIR N55°06'W 31.7' SCRIBED "CN 1/16 S28 BT"
 SET: NOTHING - ACCEPTED EXISTING USFS CORNER

⑧ **NE 1/16 SECTION S28**
 RECORD: NONE
 FOUND: STANDARD USFS MONUMENT IN MOS LS5623 (SEE NOTE)
 FWB: 8" FIR N63°05'E 6.6' SCRIBED "NE1/16 S28 BT"
 FWB: 10" FIR N71°10'W 8.9' SCRIBED "NE1/16 S28 BT"
 SET: NOTHING - ACCEPTED EXISTING USFS CORNER

⑨ **CW 1/16 SECTION 28**
 RECORD: NONE
 FOUND: STANDARD USFS MONUMENT IN MOS LS5623 (SEE NOTE)
 FWB: 12" B. OAK S58°W 11.1' SCRIBED "CW 1/16 S28 BT"
 FWB: 8" FIR N28°30'E 7.1' SCRIBED "CW 1/16 S28 BT"
 SET: NOTHING - ACCEPTED EXISTING USFS CORNER

⑩ **C 1/4 SECTION 28**
 RECORD: NONE
 FOUND: STANDARD USFS MONUMENT IN MOS LS5623 (SEE NOTE)
 FWB: 21" FIR N9°09'W 9.2' SCRIBED "C 1/4 S28 BT"
 FWB: 10" FIR S49°03'E 12.2' SCRIBED "C 1/4 S28 BT"
 SET: NOTHING - ACCEPTED EXISTION USFS CORNER

⑪ **E 1/4 SECTION 28**
 RECORD: GLO SET POST (R1)
 FWB: 6" FIR N20°E 37 LKS (R1)
 FWB: 4" FIR S48°W 50 LKS (R1)
 FOUND: NOTHING AT CORNER POINT
 FWB: 15" FIR S22°59'W 12.3' C.F. (R2)
 FWB: 18" CEDAR N68°03'E 36.5' C.F. (R2)
 FWB: RM A 3 1/4" ALM CAP W/ 2 1/2" ALM PIPE S3°40'E 13.0'
 RCE 19119 STAMPED PER MANUAL. (R2)
 SET: NOTHING - ACCEPTED EXISTING CORNER

⑫ **C 1/4 SECTION 27**
 RECORD: NONE
 FOUND: STANDARD USFS MON. IN MOS (18"x48"x48") LS5623 (SEE NOTE)
 FWB: 15" SUGAR PINE N37°36'W 16.9' SCRIBED "C 1/4 S27 BT"
 FWB: 17" FIR S9°21'W 17.8' SCRIBED "C1/4 S27 BT"
 SET: NOTHING - ACCEPTED EXISTING USFS MONUMENT

⑬ **S 1/4 SECTION 30**
 RECORD: MARKED 12" BLACK OAK FOR 1/4 CORNER (R1)
 FWB: 14" BLACK OAK N70°W 28 LKS (R1)
 FWB: 10" BLACK OAK S83°W 52 LKS (R1)
 FOUND: 16" OAK SNAG WITH VISIBLE SCRIBING (ORIG COR.)
 SET: A STD. USFS MONUMENT IN STUMP HOLE (REMOVED OLD SNAG)
 FWB: 20" FIR N11°33'E 8.9' SCRIBED "S 1/4 S30 BT"
 FWB: 9" CEDAR S59°16'W 32.0" S 1/4 S30 BT"

⑭ **SW CORNER SECTION 28**
 RECORD: 5" OAK (R1)
 FWB: 4" OAK N45°E 4 LKS (R1)
 FWB: 4" OAK N52°W 7 LKS (R1)
 FWB: 4" OAK S60°W 8 LKS (R1)
 FWB: 3" OAK S3°E 8 LKS (R1)
 FOUND: NOTHING

SET: STANDARD USFS MONUMENT IN MOS (SET BY DOUBLE PRORATE)
 FWB: 11" FIR N79°38'E 7.5' SCRIBED "T23NR6E S28 BT"
 FWB: 10" OAK S40°50'E 12.0' SCRIBED "T23NR6E S33 BT"

⑮ **W 1/16 S28/S33**
 RECORD: NONE
 FOUND: NOTHING
 SET: STANDARD USFS MONUMENT IN MOS
 FWB: 13" FIR S23°18'W 13.1' SCRIBED "W 1/16 S33 BT"
 FWB: 13" FIR N42°52'W 15.2' SCRIBED "W 1/16 S28 BT"

⑯ **S 1/4 CORNER SECTION 28**
 RECORD: GLO SET POST (R1)
 FWB: 3" FIR NORTH 14 LKS (R1)
 FWB: 12" FIR S60°W 102 LKS (R1)
 FOUND: FD STANDARD USFS MON. LS5623 (SEE NOTE)
 SET: NOTHING - ACCEPTED USFS CORNER

⑰ **SE CORNER SECTION 28**
 RECORD: GLO - SET OAK POST (R1)
 FWB: 24" FIR N40°E 24 LKS (R1)
 FWB: 40" SUGAR PINE S75°W 32 LKS (R1)
 FWB: 3" SUGAR PINE N73°W 56 LKS (R1)
 FWB: 26" SUGAR PINE S11°E 21 LKS (R1)
 FOUND: 3 1/4" ALM CAP ON 2 1/2" ALM PIPE RCE 19119 (R2)
 FWB: 52" SUGAR PINE S89°56'W 21.9' CF (R2)
 FWB: 30" FIR SNAG N38°30'E 14.7' SCRIBING VISIBLE (R2)
 FWB: 30" SUGAR PINE N65°30'W 38.9' CF (R2)
 FWB: 9" FIR S57°11'E 7.0' CF (R2)
 SET: NOTHING - ACCEPTED EXISTING CORNER

⑱ **S 1/4 CORNER SECTION 27**
 RECORD: 18" CEDAR CORNER TREE (R1)
 FWB: 19" BLACK OAK N52°W 24 LKS (R1)
 FWB: 15" BLACK OAK S6°W 30 LKS (R1)
 FOUND: 45" CEDAR CORNER TREE SCRIBING VISIBLE (ORIG COR)
 FWB: OAK STUMP HOLE N52°W 16.1'
 FWB: STANDARD USFS MON RM N10°26'21"W 13.53' LS5623 (SEE NOTE)
 FWB: 19" FIR S87°39'E 15.8' CF LS5623 (SEE NOTE)
 SET: NOTHING - ACCEPTED EXISTING USFS CORNER

⑲ **SE CORNER SECTION 27**
 RECORD: GLO - OAK POST (R1)
 FWB: 18" FIR N52°E 21 LKS (R1)
 FWB: 18" FIR N58°W 44 LKS (R1)
 FWB: 24" FIR S46°E 23 LKS (R1)
 FWB: 7" FIR S59°W 44 LKS (R1)
 FOUND: STANDARD USFS MONUMENT LS5623 (SEE NOTE)
 FWB: 34" FIR SNAG W/SCRIBING S46°38'E 15.2' (23 LKS) (R1)
 FWB: 16" FIR N43°03'E 18.4' C.F.
 FWB: 14" SUGAR PINE S63°45'W 23.4' CF

SET: NOTHING - ACCEPTED EXISTING CORNER

⑲A **SE CORNER SECTION 32**
 RECORD: STANDARD BLM MONUMENT (HAMILTON 1981)
 FWB: 11" BLACK OAK N48°E 53 LKS CF (HAMILTON 1981)
 FWB: 24" SUGAR PINE S12 1/4°E 100 LKS CF (HAMILTON 1981)
 FWB: 21" SUGAR PINE S11 1/2°W 111 LKS CF (HAMILTON 1981)
 FWB: A GRANITE BOULDER 10'X5'X6' HIGH N4°W 89 LKS
 "X" CHISELED ON SOUTH FACE. (HAMILTON 1981)
 FOUND: BLM CORNER
 SET: NOTHING - ACCEPTED BLM CORNER

SHEET INDEX

SECTIONS 28 & 27 T23NR6E MDM _____ 1 OF 4
 COR. NOTES S28 S27 T23NR6E MDM _____ 2 OF 4
 SECTIONS 19 & 29 T23NR6E MDM _____ 3 OF 4
 COR. NOTES S19 S29 T23NR6E MDM _____ 4 OF 4

ABBREVIATIONS

- ID INSIDE DIAMETER
- IP IRON PIPE
- COR CORNER
- ALM ALUMINUM
- BC BRASS CAP
- RB REBAR
- CF CLOSED FACE
- MOS MOUND OF STONE
- W/ WITH
- FD FOUND
- MKD MARKED
- P.PINE PONDEROSA PINE
- W. FIR WHITE FIR

- (R1) GLO 1875 VON SCHMIDT
- (R2) GRS78
- (R3) GLO 1938 WILSON

GENERAL NOTES

A STANDARD UNITED STATES FOREST SERVICE (USFS) DRIVE-IN MONUMENT IS A 5/8" DIAMETER ALUMINUM ROD WITH A 3-1/4" ALUMINUM CAP EDGE-MARKED WITH THE USFS LOGO.

ALL USFS CORNERS SET ON THIS SURVEY WERE STAMPED AS PER THE BLM MANUAL OF INSTRUCTIONS.

A STANDARD BUREAU OF LAND MANAGEMENT (BLM) MONUMENT IS A 2-1/2" DIAMETER STEEL PIPE, 28" LONG WITH A 3-1/2" BRASS CAP EDGE-MARKED WITH THE BLM LOGO.

ALL BLM CORNERS USED ON THIS SURVEY WERE VERIFIED AND ACCEPTED BY ME, HOWEVER, THE BLM BEARING TREES WERE NOT TIED BUT WERE CHECKED IN THE FIELD.

ALL FOUND CORNERS WITH USFS MONUMENTS SET BY ME LS5623 WERE SET IN A 1997 SURVEY REQUESTED BY THE US FOREST SERVICE FOR THE ROCK ISLAND TIMBER SALE. AT THE END OF 1997 I RETIRED WITH THE PROMISE THAT THE RECORD MAP WOULD BE DRAFTED AND RECORDED. THE MAP WAS NEVER FINISHED AND WAS NOT RECORDED THEREFORE I HAVE INCLUDED THESE CORNERS ON THIS SURVEY.

William Snow LS 5623

DGA&V LAND SURVEYOR'S

11448 SMITH RD.
 MARYSVILLE, CA. 95901
 530-742-5033

BILL SNOW 775-787-8420

RECORD OF SURVEY

SECTIONS 19,29,27,28 T23NR6E,MDM
 PLUMAS COUNTY, CALIFORNIA
 FOR
 U.S.D.A. PLUMAS NATIONAL FOREST
 159 LAWRENCE ST
 QUINCY, CA. 95971

DRAWN BY: B. SNOW DATE: DECEMBER 2011 SHEET 2 OF 4