



Received by (Print)	Kas: c McPherson	Title
Received by (Signature)		
Specialist (Print)	Specialist (Signature)	Re-inspection Date:
Thomas Fick		Nov + Routine.

Facility Name:

FUSD

PR

FAID # 150

Pg 2 of 2

Date of Inspection: 2/6/25

OBSERVATIONS AND CORRECTIVE ACTIONS

45) Ceiling is developing water spots and paint is separating/peeling.
Please move any food prep well away from any active dripping, should it occur.

- Suggest maintenance make this repair a priority due to food safety concerns.

• Glass covers in walk in cool light bulbs should be shatter-proof.

- Good sanitation observed.

Thanks

Received by (Print)

Kasie McPherson

Title

Received by (Signature)



Specialist (Print)

Dennis Eck

Specialist (Signature)



Re-inspection Date:

Next Routine