

<div>T22N R14E 1/4 S6 S5 LS 4753 2003</div> <div>CORNER No. 40</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A GENTLE NORTHWEST SLOPE IN A LOGGED AREA.</div> <div>SCRIBED AN 11" DOUGLAS FIR, N22°W, 47.2' "1/4 S6 BT" SCRIBED A 13" DOUGLAS FIR, N75°E, 50.3' "1/4 S5 BT"</div>	<div>T22N R14E 1/4 S5 S4 LS 4753 2003</div> <div>CORNER No. 41</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHEAST SLOPE IN HEAVY BRUSH AND SCATTERED TIMBER.</div> <div>SCRIBED A 9" JEFFREY PINE, S78°E, 19.5' "1/4 S4 BT" SCRIBED AN 11" DOUGLAS FIR, S36°W, 43.7' "1/4 S5 BT"</div>
<div>S 1/16 • S6 LS 4753 2003</div> <div>CORNER No. 42</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD. CORNER FALLS IN THICK TIMBER OF PONDEROSA PINE, INCENSE CEDAR AND DOUGLAS FIR NEAR AN OLD SKID ROAD.</div> <div>SCRIBED A 9" PONDEROSA PINE, S54°E, 8.1' "SE 1/16 S6 BT" SCRIBED A 6" INCENSE CEDAR, N45°E, 23.4' "SE 1/16 S6 BT"</div>	<div>T22N R14E S5 S4 S8 S9 LS 4753 2003</div> <div>CORNER No. 49</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD - NO ROCKS FOR MOUND. CORNER FALLS ON A MODERATE NORTHEAST SLOPE IN HEAVY BRUSH, 280'±SOUTH OF AN OLD JEEP ROAD.</div> <div>NO ACCESSORIES AVAILABLE</div>
<div>S 1/16 C C S6 LS 4753 2003</div> <div>CORNER No. 43</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS IN THICK TIMBER OF PONDEROSA PINE, INCENSE CEDAR AND DOUGLAS FIR ON ROCKY GROUND.</div> <div>SCRIBED A 12" PONDEROSA PINE, N48°E, 29.7' "CS 1/16 S6 BT" SCRIBED A 7" INCENSE CEDAR, S81°W, 36.4' "CS 1/16 S6 BT"</div>	<div>T22N R14E S5 S4 S8 S9 LS 4753 2003</div> <div>CORNER No. 51</div> <div>FD. A 23" PINE WITH A MOUND OF STONE AROUND BASE PER 9 R/S 24 AND 11 R/S 141. CORNER FALLS ON A GENTLE NORTHEAST SLOPE IN SCATTERED TIMBER.</div> <div>NO ACCESSORIES</div>
<div>T22N 1/4 S12 R13E 1975</div> <div>CORNER No. 44</div> <div>FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A GENTLE NORTHWEST SLOPE, 150'± SOUTH OF A ROAD.</div> <div>FD. A 50" PINE SNAG, S41 1/2°E, 27.1' -CHOPPED OUT FACE, NO VS REC. A 50" JEFFREY PINE, S41 1/2°E, 40 LKS (BLM 1975) FD. A ROTTED PINE STUMP, N68 1/2°W, 7.9' -NO VS REC. PINE STUMP REMAINS, N68°E, 11 LKS (BLM 1975) FD. A 19" PONDEROSA PINE, N62°W, 66.0' REC. A 13" JEFFREY PINE, N62°W, 100 LKS (BLM 1975)</div>	<div>N 1/16 • S7 LS 4753 2003</div> <div>CORNER No. 52</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A GENTLE SOUTHWEST SLOPE IN LAVA ROCK AND JUNIPER.</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD FOR RM, N70 1/4°E, 21.3' A BOULDER MARKED "BXO", N23 1/2°E, 55.5'</div>
<div>T22N S12 S6 S7 R13E R14E LS 4753 2003</div> <div>CORNER No. 45</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A SLIGHT NORTHEAST SLOPE IN LAVA ROCK.</div> <div>SCRIBED A 10" PONDEROSA PINE, N79 3/4°E, 44.5' "T22N R14E S6 BT" SCRIBED A 7" INCENSE CEDAR, S16 3/4°E, 59.0' "T22N R14E S7 BT"</div>	<div>S 1/16 C C S7 LS 4753 2003</div> <div>CORNER No. 53</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS A MODERATE SOUTHWEST SLOPE IN LAVA ROCK AND JUNIPER.</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD FOR RM, N53 1/2°W, 23.8' SCRIBED A 12" PONDEROSA PINE, N3°W, 85.0' "CN 1/16 S7 BT"</div>
<div>T22N R14E 1/4 S6 S7 LS 4753 2003</div> <div>CORNER No. 46</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE NORTHEAST SLOPE IN INCENSE CEDAR, PINE AND OAK.</div> <div>SCRIBED AN 11" INCENSE CEDAR, N19°W, 23.9' "1/4 S6 BT" SCRIBED AN 11" YELLOW PINE, S76°W, 12.9' "1/4 S7 BT"</div>	<div>T22N T22N S12 S7 S13 R13E R14E LS 4753 2003</div> <div>CORNER No. 54</div> <div>FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A STEEP SOUTHWEST SLOPE IN TIMBER.</div> <div>FD. A 29" PONDEROSA PINE, N72°W, 60.7' -VS REC. A 26" YELLOW PINE, N72°W, 92 LKS (BLM 1975) FD. A 22" PONDEROSA PINE, N22°E, 52.1' REC. A 21" YELLOW PINE, N22°E, 79 LKS (BLM 1975)</div>

<div>T22N R14E S6 S5 S7 S8 LS 4753 2003</div> <div>CORNER No. 47</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON THE SOUTH EDGE OF THE DIRT ROAD TO A COMMUNICATIONS SITE.</div> <div>SCRIBED A 13" PONDEROSA PINE, S33 1/2°W, 54.6' "T22N R14E S7 BT" SCRIBED A 17" PONDEROSA PINE, S62 3/4°E, 28.0' "T22N R14E S8 BT" SCRIBED A 13" PONDEROSA PINE, N48°E, 31.4' "T22N R14E S5 BT" SCRIBED A 14" PONDEROSA PINE, N61 1/2°W, 165.2' "T22N R14E S6 BT"</div>	<div>T22N R14E 1/4 S5 S8 LS 4753 2003</div> <div>CORNER No. 48</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS 40'± NORTH OF A ROAD IN HEAVY BRUSH.</div> <div>SCRIBED A 12" PONDEROSA PINE, S20°E, 28.7' "1/4 S8 BT" SCRIBED AN 11" PONDEROSA PINE, N78°W, 47.0' "1/4 S5 BT"</div>
<div>T22N R14E S5 S4 S8 S9 LS 4753 2003</div> <div>CORNER No. 49</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD - NO ROCKS FOR MOUND. CORNER FALLS ON A MODERATE NORTHEAST SLOPE IN HEAVY BRUSH, 280'±SOUTH OF AN OLD JEEP ROAD.</div> <div>NO ACCESSORIES AVAILABLE</div>	<div>T22N R14E S5 S4 S8 S9 LS 4753 2003</div> <div>CORNER No. 55</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE NORTH SLOPE AT THE EDGE OF A CLEARED AREA IN LAVA ROCK.</div> <div>SCRIBED A 7" SUGAR PINE, S55°W, 4.5' "1/4 S7 BT" SCRIBED A 19" SUGAR PINE, S79 3/4°E, 40.7' "1/4 S8 BT"</div>
<div>N 1/16 • S7 LS 4753 2003</div> <div>CORNER No. 52</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A GENTLE SOUTHWEST SLOPE IN LAVA ROCK AND JUNIPER.</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD FOR RM, N70 1/4°E, 21.3' A BOULDER MARKED "BXO", N23 1/2°E, 55.5'</div>	<div>T22N R14E 1/4 S7 S18 LS 4753 2003</div> <div>CORNER No. 58</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD NO ROCKS FOR MOUND. CORNER FALLS ON A MODERATE NORTHWEST SLOPE IN LIGHT TIMBER OF PONDEROSA PINE, SPRUCE, FIR AND CEDAR.</div> <div>SCRIBED A 22" PONDEROSA PINE, N38°E, 31.3' "T22N R14E S7 BT" SCRIBED A 15" WHITE FIR, N9°E, 60.3' "T22N R14E S7 BT"</div>
<div>T22N R14E 1/4 S7 S18 LS 4753 2003</div> <div>CORNER No. 59</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE NORTHWEST SLOPE IN A SMALL CLEARING WITH SAGE AND LAVA ROCK. SURROUNDING TIMBER IS PINE SPRUCE AND JUNIPER.</div> <div>SCRIBED AN 18" SPRUCE, N68 1/4°E, 46.2' "1/4 S7 BT" SCRIBED A 15" PONDEROSA PINE, S23 1/4°E, 37.2' "1/4 S18 BT"</div>	<div>T22N R14E S7 S8 S18 S17 LS 4753 2003</div> <div>CORNER No. 60</div> <div>SET A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A MOUND OF STONE. CORNER FALLS ON A STEEP NORTHWEST SLOPE IN HEAVY BRUSH AND SCATTERED MAHOGANY AND PINE, 150'± FROM RIDGE.</div> <div>SCRIBED AN 11" PONDEROSA PINE, S59 3/4°W, 68.5' "T22N R14E S18 BT" SCRIBED AN 8' X 5' X 4.5' BOULDER, N1°W, 24.5' "BXO"</div>

<div>CORNER NOTES</div> <div>HB = HEALED BLAZE VS = VISIBLE SCRIBING BCIP = BRASS CAPPED IRON PIPE () 1 RECORD PER 5 R/S 110 () 2 RECORD PER 9 R/S 50 () 3 RECORD PER 10 PM 86 () 4 RECORD PER 4 R/S 86 () 5 RECORD PER 4 PM 92 () 6 RECORD PER 3 PM 9 () 7 RECORD PER 2 R/S 30 () 8 RECORD PER 11 R/S 141 () 9 RECORD PER 7 R/S 26 () 10 RECORD PER 3 R/S 71 () 11 RECORD PER 8 M 33 () 12 RECORD PER 8 R/S 92 () 13 RECORD PER 11 R/S 141</div>	<div>T22N R14E 1/4 S7 S8 LS 4753 2003</div> <div>CORNER No. 71</div> <div>FD. AN ALUM. CAP ON A 1/2" REBAR PER 5 R/S 49 AND 11 R/S 141. CORNER FALLS ON A GENTLE EAST SLOPE.</div> <div>NO ACCESSORIES</div>
<div>T22N R14E 1/4 S7 S8 LS 4753 2003</div> <div>CORNER No. 72</div> <div>FD. A MOUND OF STONE PER CORNER CARD BY O. BROWN. CORNER FALLS ON A MODERATE WEST SLOPE, 75'± WEST OF A NORTH-SOUTH SPUR IN A BURN.</div> <div>SCRIBED AN 8" JEFFREY PINE, S22°W, 36.8' "T22N R13E S25 BT" SCRIBED A 5" PONDEROSA PINE, N79°W, 49.5' "X BT"</div>	<div>T22N R13E S24 S25 T22N LS 4753 2003</div> <div>CORNER No. 74</div> <div>FD. A PLASTIC CAPPED REBAR IN A MOUND OF STONE PER 11 R/S 141. CORNER FALLS IN A SAGE AND PINE FLAT, 300'± SOUTH OF A ROAD.</div> <div>NO ACCESSORIES</div>
<div>T22N R13E 1/4 S13 LS 4753 2003</div> <div>CORNER No. 76</div> <div>FD. A 1" ALUM CAP ON A 1/2" REBAR PER 6 R/S 95. CORNER FALLS ON A MODERATE SOUTHEAST SLOPE, 100'± WEST OF A MEADOW, 300'± SOUTH OF HIGHWAY 70.</div> <div>FD. A 18" PINE, S76°W, 29.9' -HB REC. A 15" PINE, S80°W, 30.15' (J9) FD. A 16" PINE, N7°E, 29.0' -HB REC. A 10" PINE, N10°E, 28.9' (J9)</div>	<div>T22N R13E S7 S8 S18 S17 LS 5623 1995</div> <div>CORNER No. 77</div> <div>FD. A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD PER 11 R/S 124. CORNER FALLS ON THE SOUTH TOE OF BANK OF OLD RAILROAD GRADE.</div> <div>FD. A 16" PONDEROSA PINE, S64°W, 57.2' -HB REC. A 14" JEFFREY PINE, S63°50'W, 57.2' (11 RS 124) FD. A 7" PONDEROSA PINE, N28°W, 9.4' -HB REC. A 6" JEFFREY PINE, N27°56'W, 9.4' (11 RS 124) FD. A 20" PONDEROSA PINE, N38°E, 38.9' -VS REC. A 19" JEFFREY PINE, N37°57'E, 38.9' (11 RS 124)</div>
<div>T22N R14E 1/4 S7 S18 LS 4753 2003</div> <div>CORNER No. 78</div> <div>FD. A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD. CORNER FALLS 3' WEST OF A FOREST ROAD.</div> <div>FD. A 16" PONDEROSA PINE, N6°W, 49.0' -HB REC. A 12" PINE, N4°42'W, 48.6' (10 R/S 83) FD. A 43" PONDEROSA PINE, S8°E, 59.0' -HB REC. A 46" PINE, S12°53'E, 60.3' (10 R/S 83)</div>	<div>T22N R13E 1/4 S8 S17 1982 LS 49516</div> <div>CORNER No. 80</div> <div>FD. A 1 1/2" ALUM CAP ON A 5/8" REBAR PER (J)11. CORNER FALLS ON A STEEP WEST SLOPE AT THE NORTHEAST CORNER OF GOLD MOUNTAIN SUBDIVISION AND THE EDGE OF A RAILROAD R/W.</div> <div>NO ACCESSORIES</div>

<div>LS 3297</div> <div>CORNER No. 64</div> <div>FD. A 3 X 3 INCH SCRIBED WOOD POST AND A PLASTIC CAPPED 1/2" REBAR IN A MOUND OF STONE PER 5 R/S 49. CORNER FALLS ON THE INSIDE OF A FENCE CORNER, 40'± SOUTH OF A DIRT ROAD.</div> <div>FD. A 23" PINE SNAG, N72 1/4°E, 8.5' FROM POST, 8.0' FROM CAPPED REBAR. REC. A 36" STUMP, N70°E, 7.0' (5 R/S 49)</div>	<div>T22N R13E S8 S9 S17 S16 1975</div> <div>CORNER No. 79</div> <div>FD. A BLM BCIP IN A SMALL MOUND OF STONE. CORNER FALLS ON A MODERATE WEST SLOPE, 40'± NORTH OF A JEEP TRAIL.</div> <div>FD. A 16" PONDEROSA PINE, S49°W, 17.8' -HB REC. 12" PINE, S49°W, 17.8' (10 R/S 49) FD. A 14" PONDEROSA PINE, N34°W, 31.0' -VS REC. A 14' PINE, N34°W, 31.0' (10 R/S 49)</div>
<div>LS 3297</div> <div>CORNER No. 71</div> <div>FD. AN ALUM. CAP ON A 1/2" REBAR PER 5 R/S 49 AND 11 R/S 141. CORNER FALLS ON A GENTLE EAST SLOPE.</div> <div>NO ACCESSORIES</div>	<div>T22N R13E 1/4 9 16 LS 2843</div> <div>CORNER No. 81</div> <div>FD. A 1 1/2" ALUM CAP ON A 5/8" REBAR PER 9 R/S 19 IN A MOUND OF STONE. CORNER FALLS ON A GENTLE NORTH SLOPE, 60'± NORTH OF A PAVED ROAD AND 200'± NORTH OF PUTTING GREEN.</div> <div>NO ACCESSORIES</div>
<div>LS 5623</div> <div>CORNER No. 74</div> <div>FD. A PLASTIC CAPPED REBAR IN A MOUND OF STONE PER 11 R/S 141. CORNER FALLS IN A SAGE AND PINE FLAT, 300'± SOUTH OF A ROAD.</div> <div>NO ACCESSORIES</div>	<div>T22N R13E S9 S10 S16 S15 1975</div> <div>CORNER No. 82</div> <div>FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A MODERATE NORTHWEST SLOPE, 120'± EAST OF THE TOP OF AN OPEN KNOB.</div> <div>FD. A 20" PONDEROSA PINE, S80°W, 27.1' -HB REC. A 14" PINE, S80°E, 27.1' (9 R/S 19) FD. A 13" PONDEROSA PINE, S82°E, 24.4' -HB REC. A 9" PINE, S82°E, 24.4' (9 R/S 19) FD. A 22" PONDEROSA PINE, N20°W, 44.2' -VS REC. A 19" PINE, N20°W, 44.2' (9 R/S 19)</div>
<div>LS 2843</div> <div>CORNER No. 76</div> <div>FD. A 1" ALUM CAP ON A 1/2" REBAR PER 6 R/S 95. CORNER FALLS ON A MODERATE SOUTHEAST SLOPE, 100'± WEST OF A MEADOW, 300'± SOUTH OF HIGHWAY 70.</div> <div>FD. A 18" PINE, S76°W, 29.9' -HB REC. A 15" PINE, S80°W, 30.15' (J9) FD. A 16" PINE, N7°E, 29.0' -HB REC. A 10" PINE, N10°E, 28.9' (J9)</div>	<div>T22N R16E N 1/16 S18 S17 LS 5623 1991</div> <div>CORNER No. 83</div> <div>FD. A 3 1/4" ALUM. CAP ON A 3/4" ALUM ROD IN A SMALL MOUND OF STONE. CORNER FALLS ON A MODERATE NORTHWEST SLOPE IN THICK REPRODUCTION TIMBER.</div> <div>FD. A 12" PONDEROSA PINE, N45 1/2°W, 21.4' -HB NO RECORD FD. AN 11" CEDAR, S57°W, 21.9' -VS NO RECORD</div>

RECORD OF SURVEY


FOR

USDA FOREST SERVICE

PLUMAS NATIONAL FOREST

"MAYBIE"

IN SECTIONS 34, 35 AND 36, T. 23 N, R. 13 E.,
SECTION 31, T. 23 N, R. 14 E.,
SECTION 25, T. 22 N, R. 12 E.,
SECTIONS 16, 17, 18, 28, 29, 30 AND 33,
T. 22 N, R. 13 E.,
SECTIONS 5, 6, 7, 8 AND 9, T. 22 N, R. 14 E.,
AND SECTIONS 3 AND 4, T. 21 N, R. 13 E., M.D.M.,
IN THE UNINCORPORATED AREA OF PLUMAS COUNTY,
STATE OF CALIFORNIA

DEL TERRA INC.
SURVEYING
1168 INDUSTRIAL ST.
REDDING, CA 96002
PHONE (530) 241-8050

SCALE: NONE
DATE: AUGUST, 2003
SHEET 8 OF 11