

CORNER RECORD

Agency Index 457
 Document Number _____

City of _____ County of Plumas, California
 Brief Legal Description N 1/4 of Sec 17, T26N R14E MDM

CORNER TYPE			COORDINATES (Optional)		
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	N. <u>1929198.50</u>	E. <u>7001624.91</u>	
Government Corner			<input checked="" type="checkbox"/> Control	<input type="checkbox"/> Elevation	
Meander			<input type="checkbox"/> Property	<input type="checkbox"/> Units	Metric <input type="checkbox"/> U.S. Survey Foot <input checked="" type="checkbox"/>
Rancho			<input type="checkbox"/> Other	<input type="checkbox"/> Horizontal Datum	<u>NAD 83</u>
Date of Survey <u>May 26, 2021</u>			Zone <u>CA 1</u>	Epoch Date	<u>2011</u>
			Vertical Datum		
			<input type="checkbox"/> Complies with Public Resources Code §§8801-8819		
			<input type="checkbox"/> Complies with Public Resources Code §§8890-8902		
PLS Act Ref.:	<input type="checkbox"/> 8765(d)	<input type="checkbox"/> 8771	<input checked="" type="checkbox"/> 8773	<input type="checkbox"/> Other:	
Corner/ Monument:	<input type="checkbox"/> Left as found	<input type="checkbox"/> Established	<input checked="" type="checkbox"/> Rebuilt	<input type="checkbox"/> Pre-Construction	
	<input type="checkbox"/> Found and tagged	<input type="checkbox"/> Reestablished	<input type="checkbox"/> Referenced	<input type="checkbox"/> Post-Construction	

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on November 18, 2024.

Signed Kam Kozloski P.L.S. or R.C.E. No. 8972



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 11/14/24

and examined and filed 12/6/24.

Signed R. Tom Shurtliff P.L.S. or R.C.E. No. 30515

Title CONTRACT COUNTY SURVEY

County Surveyor's Comment



Found 3'x3'x1' stone mound w/ K-tag dated 1970 on top. Did not find original 18x12x10 "1/4" marked stone. Accepted stone mound as best available evidence after thorough search of area. Set 2" alum. pipe w/ 3" cap in center of stone mound.

T26N R14E
1/4
S8

S17
LS 8972
2021

S $28^{\circ}03'E$ 85.0

New Bearing Tree:
20" Yellow Pine

