

## CORNER RECORD

2

COUNTY OF PlumasT. 23 N.R. 7 E

MD B&amp;E

MERIDIAN

CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER 

CORNER IDENTIFICATION — DATE OF VISIT

11/6/74

19

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT 

## PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

3/4" I. PIPE AND 1/4" REBAR IN ROCK MOUND. NO. BT'S

## PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

TAGGED 3/4" I. PIPE RCE 13528

## CALIFORNIA COORDINATE SYSTEM ORDER:

STATIONS USED: NGS (USC & GS) FIRST SECOND THIRD STATE COUNTY OTHER 

STATION

BUCK A

STATION BUCKHORN A

ZONE 1 ELEVATIONNORTHINGS (Y) 196 214.426EASTINGS (X) 2 232 208.295

## SKETCH: (Include reference tie or witness points, remarks and topo of area)

## SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 11-28 1977

SIGNED:

R.C.E. No.: 13528

SEAL

## COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 11-28-77 1977  
AND EXAMINED AND FILED 11-28-77 1977

BY:

TITLE: County SurveyorDOCUMENT NO. 10

STATEMENT ON BACK OF SHEET

YES NO