


## CORNER RECORD

(5)

COUNTY OF Plumas T. 23 N R. 7 E MD B&M MERIDIAN CALIFORNIA  
 CORNER TYPE: GOVT. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
 CORNER IDENTIFICATION — DATE OF VISIT 12/18/ 1977



SECTION CORNER

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

## PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND  $1\frac{1}{2}$ " INSIDE DIAMETER IRON PIPE IN MOUND OF GRANITE ROCK IN A BRUSH FIELD  
 WITH TWO "K" TAGGED AND MARKED BEARING TREES 1. B.T. 31" P.P. N.  $80^{\circ}$ W. 53 LKS.  
 2. B.T. 10" W.F. N.  $34^{\circ}$ E. 10 LKS.


## PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

MONUMENT  
 LEFT AS FOUND

SET A 100" SPIKE W/ STAKE MARKED PI 28-1B CALIF GRID N  $68^{\circ}25'31''$ W  
 97.68' FROM FOUND CORNER.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
 STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_  
 ZONE 1 ELEVATION NORTHINGS (Y) 196, 193.79 STATION EASTINGS (X) 7,216,894.81

## SKETCH: (Include reference tie or witness points, remarks and topo of area)



## SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY  
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT  
 ON 12/15 1977

SIGNED: Lawrence J. Brack  
 L.S. or R.C.E. No.: R.C.E. 1352

SEAL

## COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 12-23-77 1977  
 AND EXAMINED AND FILED 12-23-77  
 BY: Lawrence J. Brack  
 TITLE: C. of Eng.

DOCUMENT No. 13

STATEMENT ON BACK OF SHEET

YES  NO


Index E-5  
File No.

T 7.3 N. R. 7 E.  
Merid. M. D.

## CORNER RECORD (SEARCH)

Tract or  
Survey No.Cor.  
No. E-5R.D. MERRIMAC County Plumas  
N.F. Plumas State California

## CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND A post was set by original  
surveyor. This is no longer to be found.

## PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By \_\_\_\_\_  
Signature

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_  
Agency \_\_\_\_\_

Signature

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

1. P.P. 3 1/2" N 80°W 53 lbs. Olive. Grown over.
2. Monzanita (5") N. 8°E. 4 lbs. Grown.
3. P.P. (6") S:45°W 16 lbs. Grown.
4. P.P. (3") S. 48°E. 10 lbs. Grown.

Mound of stone located around point.

## DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner in brush field. B.T. visible from county road.  
Posters as shown in sketch.

4  
7100-52  
REV. 65 5

Title

Division

Headquarters

Date

Signature  
John W. Ahernholz

For.

R/W

Quarry

6/27/67