


CORNER RECORD

City of _____

Document Number _____

County of PLUMAS, California
Brief Legal Description LOT 3, BLOCK 12, GRAEAGLE SUBDIVISION No. 1, SEC. 16, T22N, R12W, MDM.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey September 24, 1992

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 3/4" Round headed bolt type rods for Corners on Lot 3 and for most Northerly Corner of Lot 2, Block 12. used said corners to establish most Northerly corner of Lot 3 in record position

A description of the physical condition of the monument as found and as set or reset: Set 5/8" Rebar with Plastic Cap at record position between found corners

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Oct. 20 1992.

Signed John W. Hamby L.S. or R.C.E. Number L.S. 2843



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined
and filed Oct 27 1992.

Signed R. Tom Shute Title County Engineer



County Surveyor's Comment _____

LEGEND

- Found 3/4" round head bolt type Rod
- Set 5/8" Rebar with Plastic Cap (522943)
- Nothing found

