


CORNER RECORD

Document Numbr _____

County of Plumas, California

City of _____
 Brief Legal Description Section Corner to Sections 21, 22, 28 and 27. T. 22 N.
R. 14 E., M.D.M.



CORNER TYPE

Government Corner

Control

Meander

Property

Rancho

Other

Date of Survey 5/28/92

COORDINATES (Optional)

N. _____

E. _____

Zone _____ Datum _____

Elev. _____

Corner Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Government Section Corner to Sections 21, 22, 28 and 27. Found K-tag on 21" cedar marked "Wood Post Mound Stone BRS S 30° E 13 feet." Corner position verified by: G.L.O. record data, Volume 5 of Record of Surveys Page 49 Data and Volume 8 of Record of Surveys Page 135 Data (see sketch attached).

A description of the physical condition of the monument as found and as set or reset: Found 3 ft. diameter stone mound with remains of a wood post adjacent to mound. Set 3/4" iron pipe with 2-1/2" brass cap in 3 ft. diameter mound of stones; bears N 28° W 14.6 feet to 21" cedar, bears N 73 E, 33.5 feet to 12" cedar, bears S 33° E, 31.3 feet to 9" pine, bears S 68° W, 20.1 feet to 12" pine.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on November 16 1992.

Signed Larry A. Fites S. or R.C.E. Number 13225



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 1/5 1993 and examined

and filed 1-5 1993.

Signed R. Tom Shantz Title Co. Surveyor

County Surveyor's Comment _____

/







LEGEND

- ◊ SECTION CORNER,
SEE BRS 135 FOR
DESCRIPTION.
- ()¹ GLO DATA FROM
1863 AND 1875
GLO SURVEYS.
- ()² S.R.S. 135

BASIS OF BEARINGS:

THE BEARING OF S 87° 34' 40" E
FOR THE SOUTH LINE OF SECTION
27, T. 22 N. R. 14 E.



NOTE: ALL BT SCRIBED
PER THE MANUAL.

DETAIL