

# CORNER RECORD


City of \_\_\_\_\_

Brief Legal Description SW COR. SEC. 8

Document Number \_\_\_\_\_

County of PLUMAS, California

T 21 N R 12 E MDM



## CORNER TYPE

Government Corner

Control

N. \_\_\_\_\_

Meander

Property

E. \_\_\_\_\_

Rancho

Other

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey \_\_\_\_\_

Elev. \_\_\_\_\_

## COORDINATES (Optional)

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 3 GLO BEARING TREES, 2 IN GOOD CONDITION WITH HEALED SCARS, 1 SNAG WITH VISIBLE SCRIBING (SEE OVER→)

A description of the physical condition of the monument as found and as set or reset:

FOUND A STONE MOUND IN GOOD CONDITION SET A STD. U.S.F.S. ALUM. MON. IN EXISTING MOUND (SEE BOOK 10 OF MAPS & SURVEYS PAGES 24 & 25, SIERRA COUNTY RECORDS)

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on FEBRUARY 21, 1995.

Signed Fred W. Cook L.S. or R.C.E. Number L5 3966



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2/23 1995 and examined

and filed 2/28 1995.

Signed R. Tom Shumate Title C. Surveyor



County Surveyor's Comment \_\_\_\_\_

