


CORNER RECORD

COUNTY OF Plumas T. 24 N R. 9 E SECTION 24 MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT OCT 1995 (PROPERTY)



CORNERS FOR LOTS 7 & 12 WITHIN CLAREMONT VILLAGE ADDN #5
 4 RM 119

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

SW COR: LOT 12: FOUND $\frac{1}{2}$ " RE-BAR AT RECORD LOCATION, PLACED ALUMINUM CAP "RCE 13528"

NW COR: LOT 12: FOUND NOTHING, SET $\frac{1}{2}$ " REBAR CAPPED "RCE 13528"

SW COR: LOT 7: FOUND NOTHING, SET $\frac{1}{2}$ " REBAR CAPPED "RCE 13528"

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED FOUND

NW COR LOT 7: $\frac{1}{2}$ " REBAR PLASTIC CAP WS. 3297

NW COR LOT 13: $\frac{1}{2}$ " REBAR PLASTIC CAP WS 3297

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

SEE REVERSE



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 12-12 1995

SIGNED: Lawrence J. Brock
 R.C.E. No.: 13528

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 12/13 1995 AND EXAMINED AND FILED 12/20 1995

BY: R. Tom Shumate
 TITLE: Co. Surveyor

DOCUMENT No. #117

STATEMENT ON BACK OF SHEET

YES NO

