

CORNER RECORD


Document Number _____

Section 35, T.23N.R.13E.

County of Plumas

, California

Brief Legal Description Lot 3, Block 5, PORTOLA HEIGHTS Book 5 RS 86



CORNER TYPE

Government Corner Control

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey 6-9-1999

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Monuments in Record position per 5 RS 86 as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset:


Monuments found were reset monuments per 5 RS 86 and appeared to be in original condition.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on (Month day), 1999.

Signed John W. Hamby L.S. 2843
John W. Hamby

619



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 7/12 1999 and

examined and filed 7/13 1999.

Signed R. Tom Hunter Title County Surveyor

County Surveyor's Comment _____

A portion of Block 5, PORTOLA HEIGHTS.



GRIZZLY AVE.

LOT 3
PORTOLA HEIGHTS

Portion of Section 35
T.23N.R.13E. M.D.M.
Plumas County Calif.
Scale 1" = 50' June 1999

LEGEND

- FOUND Rebar with Aluminum Cap LS 2843
- FOUND Rebar with Plastic Cap LS 2843
- SET 5/8" Rebar & Plastic Cap LS 2843
- (R1) RECORD per 5 rs 86.

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571