


CORNER RECORD

Document Number 217

City of _____

County of PLUMAS, California

Brief Legal Description SE COR PARCEL 2, 11 PM 54, T26N R9E S1



CORNER TYPE

Government Corner	<input type="checkbox"/>	Control	<input type="checkbox"/>
Meander	<input type="checkbox"/>	Property	<input checked="" type="checkbox"/>
Rancho	<input type="checkbox"/>	Other	<input type="checkbox"/>

COORDINATES(Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elevation _____

Vert. Datum: NGVD29 NAV88

Meas. Units: Metric Imperial

Date of Survey JULY 1, 2002

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE MAP ON REVERSE

A description of the physical condition of the monument as found and as set or reset:

See MAP ON REVERSE

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JULY 22, 2002.

Signed Richard Knoettgen P.L.S. or R.C.E. Number L 7794



COUNTY SURVEYORS STATEMENT


This Corner Record was received July 30, 2002 and examined

and filed August 6, 2002.

Signed R. Tom Shantz P.L.S. or R.C.E. Number 30515

Title County Surveyor

County Surveyor's Comment _____



SCALE

1 INCH = 30 FEET

PARCEL 2

(11 PM 54)

500°05'19" W

PARCEL 1

(11 PM 54)

FOUND 3/4" OD IP WITH
BRASS TAG RCE 26870
6 PM 91 5063

6 PM 91

191 50.67
50.85

FOUND 1/2" REBAR WITH YELLOW
PLASTIC CAP RCE 22836 (11 PM 54)
6" BELOW GROUND

N76°33'43" W (11 PM 54)

163.06
163.40 (11 PM 54)

RCE 26810

FOUND 3/4" OD IP WITH
BRASS TAG RCE 26870
6 PM 91