

## CORNER RECORD

Section 8, T.22N.R.13E M.D.M.


Document Number

218

County of Plumas

, California

Brief Legal Description Portion Parcel 2, 10 PM 64



## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey July 15, 2002

Elev. \_\_\_\_\_

Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
 Found monuments shown on the attached sketch in good condition and as shown on  
 the map filed in the office of the Recorder of Plumas County in Book 10 PM 64.


A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with aluminum cap stamped LS 2843 as indicated on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in  
conformance with the Land Surveyors' Act on July, 15, 2002Signed John W. Hamby L.S. 2843  
John W. Hamby

## COUNTY SURVEYOR'S STATEMENT


This Corner Record was received July 31 2002 and  
examined and filed August 6 2002.Signed R. Tom Shute Title County Surveyor

County Surveyor's Comment \_\_\_\_\_

- FOUND 1/2" Rebar with Aluminum Cap RCE 13225
- SET 5/8" Rebar & Aluminum Cap LS 2843

(R1) RECORD per 10 PM 64

Parcel 1



Parcel 2

N02°45'01"E  
280.60' (R1)

Portion parcels 1 & 2  
per Parcel Map 10 PM 64

Portion Section 8, T.22N.R.13E. M.D.M.  
Plumas County California  
Scale 1"=100' July 2002

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571