

CORNER RECORD

Document Number


243

Portion Section 26, T.23N.R.14E.

County of Plumas

, California

Brief Legal Description Lots 3,4 &5 Block 3 Kelseys Addition to Beckwourth



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey July, 28, 2003COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found corner monuments as indicated on the attached sketch, and set corners as indicated.

A description of the physical condition of the monument as found and as set or reset: *The found corners were in good condition and in proper locations or as shown.*

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on July 28, 2003.

Signed J.W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received August 1 2003 and examined and filed August 5 2003.

Signed R. Tom Stanton Title County Surveyor



County Surveyor's Comment _____

- FOUND point as described
- FOUND Rebar with Aluminum Cap LS 2843
- SET 5/8" Rebar & Aluminum Cap LS 2843
- ☒ FOUND 3/4" I.P. tagged L.S. 6051
- Nothing found or set
- (R1) RECORD per 7 RS 148
- (R2) RECORD per 9 RS 136



BLOCK 3
KELSEY'S ADDITION
TO BECKWOURTH
Portion Sec. 26
T.23N., R.14E. M.D.M.
Scale 1"=100'

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571