


# CORNER RECORD

APN  
City of 116-350-002

Brief Legal Description CRAWFORD ESTATES SUBDIVISION, EAST QUINCY, 519 T24N R10E

Document Number 249

County of PLUMAS, California



## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other

## COORDINATES(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elevation \_\_\_\_\_

Date of Survey OCTOBER 23, 2003

Vert. Datum: NGVD29  NAV88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE BACK SIDE


A description of the physical condition of the monument as found and as set or reset:

SEE BACK SIDE

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyor's Act on OCTOBER 30, 2003.

Signed Richard Knoettgen P.L.S. or R.C.E. Number L 7794  
For the State of California  
Department of Transportation



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 31, 2003 and examined  
and filed November 12, 2003.

Signed R. Tom Shuster P.L.S. or R.C.E. Number 30515

Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_

