

CORNER RECORD

Document Number


263

IN THE NE1/4 OF SEC. 8, T.22N., R12E., M.D.M.

County of PLUMAS

, California

Brief Legal Description LOT 35 OF PLUMAS-EUREKA ESTATES, UNIT NO. 2; 4 M 96-97



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey FEBRUARY 4, 2004

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND POINTS AS SHOWN AND DESCRIBED ON ATTACHED SKETCH AND AS SHOWN ON 4 M 96-97


A description of the physical condition of the monument as found and as set or reset:

FOUND POINTS AS DESCRIBED AND IN GOOD CONDITION. POINTS SET AS SHOWN ON ATTACHED SKETCH.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on February 4, 2004.

Signed J W Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2-5 2004 and
 examined and filed February 6 2004.


Signed R Tom Shultz Title Engineer



County Surveyor's Comment _____



1" = 100'



COUNTY SURVEYOR'S STATEMENT

LEGEND

- FOUND 1/2" Rebar
- SET 5/8" Rebar & Aluminum Cap LS 2843

All data is Record and Measured per 4 M 96-97

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571