


## CORNER RECORD

Document Number 289

IN THE SE1/4 OF SEC. 10, T.22N., R.12E., M.D.M. County of PLUMAS, California

Brief Legal Description A PORTION OF THE LOT SHOWN ON 5 RS 51 AND AS DESCRIBED  
IN 291 O.R. 91

## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey JULY 28, 2003

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND POINTS AS SHOWN AND DESCRIBED ON ATTACHED SKETCH AND AS SHOWN ON  
5 RS 51 AND 12 RS 110.

A description of the physical condition of the monument as found and as set or reset:

FOUND POINTS AS DESCRIBED AND IN GOOD CONDITION. POINTS SET AS SHOWN ON  
ATTACHED SKETCH.


## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in  
conformance with the Land Surveyors' Act on Sept. 24, 2003.Signed John W. Hamby L.S. 2843  
John W. Hamby

## COUNTY SURVEYOR'S STATEMENT


This Corner Record was received April 8<sup>th</sup> 2005 and  
examined and filed May 31, 2005.Signed Tom Shultz Title Engineer

County Surveyor's Comment \_\_\_\_\_





1" = 40'



#### LEGEND

- FOUND PK nail or as noted per 5 RS 51 & 12 RS 110.
- SET 5/8" Rebar & Aluminum Cap LS 2843
- NOTHING FOUND
- (R1) Record per 5 RS 51
- (M) Measured

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571