


CORNER RECORD

Document Number 292

Section 8, T. 22 N., R. 12 E., M.D.M.

County of Plumas

, California

Brief Legal Description Lot 20, Plumas Eureka Estates, Unit No. 7 (Phase 1), 5 M 50
see also 8 RS 148.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 9-16-03

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found corners of Lot 20 as shown in sketch and set Northwest corner in record position, next corner to West would be in drainage ditch and could not be found.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with Aluminum Cap LS 2843 in record position.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on September 17, 2003.

Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 8th 2005 and
 examined and filed May 31, 2005.

Signed R. Tom Shumate Title Engineer



County Surveyor's Comment _____


LEGEND

- FOUND 5/8" rebar with Plastic Cap LS 5055 per 8 RS 148.
- SET 5/8" Rebar with Aluminum Cap LS 2843
- Nothing Found or Set

(R1) Record per 5 M 50. (M) Measured

Scale 1" = 30'

Scale 1" = 30'



Lot 20, Plumas Eureka Estates
Unit No. 7 (Phase I)

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571