


CORNER RECORD

Document Number

301

SW1/4 OF NW1/4 OF SE1/4, Sec 24, T.22N.R.12E MDM County of PLUMAS, California

Brief Legal Description Southwest parcel of Parcel on 1 PM 76.



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey April 5, 2005

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found points marked as shown on attached sketch in locations shown.

A description of the physical condition of the monument as found and as set or reset:

Found points as indicated in good condition. Set point as indicated on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 5, 2005.

Signed John W. Hamby L.S. 2843
John W. Hamby

(18)

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received May 31st 2005 and examined and filed August 8 2005.Signed R. Tom Slantz Title County Surveyor

County Surveyor's Comment _____




- FOUND point as described
- SET 5/8" Rebar & Aluminum Cap LS 2843

(R1) RECORD per 1 PM 76



Center Sec. 24.

APN 123-130-001
Scale 1"=300'



Fd. 3/4" IP
LS 2846 **Norris**
set plug for Grimes
RCE 7294

Southwest Parcel of
Parcels on 1 PM 76

PLUMAS COUNTY, CALIF.
SCALE 1"=300' APRIL 2005

05039

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571