

## CORNER RECORD


Document Number

304

Section 17, T.21N., R.9E., M.D.M.

County of Plumas, California

Brief Legal Description Lot 110, LA Porte Pines Country Club, 2 Maps 71, Plumas County records.



## CORNER TYPE

Government Corner  Control 

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey 8-02-05

Elev. \_\_\_\_\_

COORDINATES  
(Optional)Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found most Northerly corner of Lot 110 and Southeast corner of Lot 106 from which I set the most Easterly corner of Lot 110 in record position as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset:

Found 1 1/2" I.P. tagged RCE 8850 at most Northerly corner of Lot 110 and 1/2" rebar at most Easterly corner of Lot 106 as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August 3, 2005.


Signed John W. Hamby L.S. 2843  
John W. Hamby

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Aug. 8<sup>th</sup> 2005 and  
examined and filed August 16 2005.Signed R. Tom Stanton Title County Surveyor

County Surveyor's Comment \_\_\_\_\_

NOTE: All bearings and distances shown are measured and record per 2 M 71.



Lot 110, La Porte Pines  
Country Club, 2 M 71

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571

05151