

CORNER RECORD

Document Number 319

Section 11, T. 24 N. R. 9 E. M.D.M.

County of Plumas, California CKBrief Legal Description East line of Parcel 3, 11 PM 12

CORNER TYPE		COORDINATES (Optional)	
1	1	Government Corner <input type="checkbox"/>	Control <input type="checkbox"/>
	X	Meander <input type="checkbox"/>	Property <input checked="" type="checkbox"/>
		Rancho <input type="checkbox"/>	Other <input type="checkbox"/>
Date of Survey <u>December 29, 2005</u>		N. _____	
		E. _____	
		Zone _____	Datum _____
		Elev. _____	

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
 Found 1/2" Rebars with Plastic Caps, RCE 22836 in record locations
 shown attached sketch.

A description of the physical condition of the monument as found and as set or reset:

Found 1/2" Rebars with Plastic Caps, RCE 22836 in good condition.

Set 5/8" Rebar with Al. Caps, LS 5620 in record position as
 shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
 conformance with the Land Surveyors' Act on January 11, 2006.Signed John L. Owen L.S. 5620.
 John L. Owen

1-11-06

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Jan-12th 2006 and
 examined and filed Feb 14th 2006.Signed Tom Shantz Title County Surveyor

County Surveyor's Comment _____



Center 1/4 Section 11
Found 1/2" Rebar with
Plastic Cap, RCE 22836

LEGEND

- FOUND point as described
- SET Rebar with Aluminum Cap LS 5620

Note:
Bearings and Distances
are Record and Measured
per 11 PM 12

Found 1/2" Rebar with
Plastic Cap, RCE 22836

S89°56'03"E
698.70'

S00°09'41"W
223.89'

Brownlee Resulting
Parcel 1

Brownlee Resulting
Parcel 3

Brownlee Resulting
Parcel 2

S39°50'19"E
1204.77'

Parcel 4A
L.L.A. 761 O.R. 215

Corner Record for Ed Brownlee

A portion of the S 1/2 of Section 11
T. 24 N., R. 9 E., M.D.M.
Plumas County ~ California
Scale 1" = 200' January, 2006

1" = 200'

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571

05295