


CORNER RECORD

Document Number 367

City of Portola

County of Plumas

, California

Brief Legal Description Lot 17 & 18, Block 6, Portola Townsite - S.36, T.23N. R.13E.

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey _____

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found points shown on attached sketch in good condition per 13 RS 101.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" Rebar with Aluminum Cap LS 5620 in locations shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on February 13, 2008.

Signed John L. Owen L.S. 5620
John L. Owen

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 3rd 2008 and
examined and filed April 11th 2008.Signed R. Tom Shuster Title County Surveyor

County Surveyor's Comment _____

All bearings and distances are record, calculated and measured per 13 RS 101 (R1)



1" = 50'

