

## CORNER RECORD

Document Number

372

T. 23 N., R 14 E. S. 16 MDM

County of Plumas

, California

Brief Legal Description Lot 139, 140, &amp; 141 Grizzly Ranch Unit 3, 9 M 128


## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey July 25, 2008

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found Rebar with Aluminum Cap, LS 2843, at locations shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset:


Set Nail and tag LS 5620 at Westerly Corner common to Lots 139 &amp; 140.

Set 5/8" rebar with Aluminum Cap LS 5620 at most Northerly corner of Lot 141  
as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in  
conformance with the Land Surveyors' Act on August 6, 2008.Signed John L. Owen L.S. 5620  
John L. Owen

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Aug. 11, 2008 and  
examined and filed 2008.Signed Tom Slawter Title County Surveyor  
RCE 30515

County Surveyor's Comment \_\_\_\_\_


All Bearings and Distances are Record and Measured per 9 M 128



LINE TABLE		
LINE	BEARING	LENGTH
L1	N79°51'09"E	24.07'

CURVE TABLE			
CURVE	LENGTH	RADIUS	DELTA
C1	95.56	50.00	109°30'32"
C2	35.27	50.00	40°24'58"
C3	34.97	50.00	40°04'02"

1" = 100'



#### LEGEND

- FOUND Rebar with Aluminum Cap LS 2843
- SET Nail & tag LS 5620
- ◐ SET 5/8" Rebar & Aluminum Cap LS 5620