


CORNER RECORD

Document Number 375

✓ T. 23 N., R 14 E. S. 21 MDM

County of Plumas

, California

Brief Legal Description Lot 238 & 239 Grizzly Ranch Unit 5, 10 M 38 ✓

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey July 25, 2008

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
✓ Found Rebar with Plastic Cap, LS 6469, at locations shown on attached sketch.A description of the physical condition of the monument as found and as set or reset:
Set 5/8" rebar with Aluminum Cap, LS 5620, at location shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on September 16, 2008.

Signed John L. Owen L.S. 5620

John L. Owen



9-16-08

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Sept. 18, 2008 and
examined and filed Oct. 31 2008.Signed R. Tom Stanton Title County Surveyor

County Surveyor's Comment _____

All Bearings and Distances are Record and Measured per 10 M 38

