

28R 7R 33S

CORNER RECORD


County of Plumas

Document Number: 377

County of: Plumas, California

Brief Legal Description:

Lot 143, Lake Almanor West Unit No.1, 4 M 47 Plumas County records



CORNER TYPE

Government Corner Control

Meander Property

Rancho Other

COORDINATES (Optional)

N. _____
E. _____

Zone: _____ NAD27 NAD83

NAD83 Epoch: _____
Elevation: _____

Vert. Datum: NVGD29 NAVD88

Meas. Units: Metric Imperial

Date of Survey: November 7, 2008

Corner: Left as Found Found and Tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

✓ Found 1/2" pipe with brass tag, L.S. 3202, at locations shown on the attached plat.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with plastic cap at Northerly corners of lot 143 as shown on the attached plat.

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Action: November, 12 2008.


Signed:  P.L.S. or R.C.E. Number: R.C.E. 29113



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received on Nov. 13, 2008
and examined and filed on Nov 25, 2008.

Signed:  P.L.S. or R.C.E. Number: RCE 30515
Title: County Surveyor EXP. 3/31/2010



County Surveyor's Comments:

LEGEND

- FOUND 1/2" IRON PIPE TAGGED L.S. 3202 PER 4 M 47
- ☒ FOUND 1/2" O.I.P.
- CALCULATED POINT, NO MONUMENT FOUND OR SET
- SET 5/8" REBAR AND PLASTIC CAP R.C.E. 29113
- ✓ (R) RECORD DATA PER 4 M 47
- (C) CALCULATED
- (M) MEASURED

SCALE 1"=60'

145 PARCEL NUMBER PER 4 M 47

