

CORNER RECORD

City of near Whitehawk

Agency Index 431

Document Number _____

County of Plumas, California

Brief Legal Description North 1/16th, S3 and S2, T21N, R12E Mount Diablo Meridian

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units _____ Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Date of Survey 9-26-2018

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref: 8765(d) 8771 8773 Other:

Corner/ Left as found Established Rebuilt Pre-Construction
 Monument: Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description (s):

Found $\frac{5}{8}$ " Aluminum Rod with $3\frac{1}{4}$ " Aluminum Cap in rock mound, per 10RS101.

Monument in excellent condition. Rebuilt and added to rock mound, 3' diameter, 8" in height.
 Set new bearing tree. Painted rocks red. Set post with 54-2 & 54-9 sign 2' southerly of monument.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on 11/29/18

Signed ALAN D. FRANK P.L.S. or R.C.E. No. P.L.S. 7172



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2/27/19
 and examined and filed 7/30/19
 Signed R. Tom Shultz P.L.S. or R.C.E. No. 30515
 Title COUNTY SURVEYOR



County Surveyor's Comment _____

Refreshed and Repainted
8" Cedar, painted blaze and ring.
54-3 sign. Mag Spikes for bearing
and distance. 54-9 sign on
back of tree.

() INDICATES RECORD
DATA PER 10RS101

NOT TO SCALE

N 57° 40' W
8.9'
MEASURED
RECORD
AND
RECORD
PER
10RS101

1315.73'
(1315.72')

1359.92'
(1359.91')

NE 1/16
S3
•
LS 3966
1993

N 1/16
S3 | S2
LS 3966
1993

NW 1/16
S2
•
LS 3966
1993

S 17° 41' W
6.2'
Set new bearing tree, a
14" Douglas Fir, blazed and
scribed "N 1/16 S3 BT", etched 6"
ring 6' above ground,
painted blaze and ring red.
54-3 sign. Mag Spikes for
bearing and distance.
54-9 sign on back of tree.

12" Douglas Fir
Dead Snag - Left as is.

