

CORNER RECORD


City of near Whitehawk

Agency Index 440

Document Number _____

County of Plumas, California

Brief Legal Description East 1/4, S1, T21N, R12E Mount Diablo Meridian



CORNER TYPE

COORDINATES (Optional)

Government Corner Control
 Meander Property
 Rancho Other

N. _____ E. _____

Elevation _____

Units _____ Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Date of Survey 10-12-2018

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref: 8765(d) 8771 8773 Other:

Corner/
Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description (s):

Found 2½" steel pipe with 3¼" brass cap in rock mound, per 9RS107.

Monument is in excellent condition. Rebuilt rock mound 3' in diameter, 4" in height. Set new bearing tree. Painted rocks red. Set post with 54-2 & 54-9 sign, 2' southwesterly.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on 11/29/18

Signed R. Tom Slants P.L.S. or R.C.E. No. P.L.S. 7172




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2/29/19

and examined and filed 7/30/19

Signed R. Tom Slants P.L.S. or R.C.E. No. 30515

Title County Surveyor



County Surveyor's Comment _____

Set new bearing tree, a
6" White Fir, blazed and scribed
"E 1/4 S1 BT", etched 6" ring 6' above ground,
painted blaze and ring red, 54-3 sign,
Mag Nail Spikes for bearing and distance,
54-9 sign on back of tree.

Refreshed and Repainted
38" Cedar, painted blaze
and ring red. Mag Spike for
bearing and distance.
54-9 sign on back of tree.

