

# RECORD OF SURVEY


OF A PORTION OF THE BOUNDARIES OF THE  
**LANDS OF W.H. & JOE N. LEE**  
 IN SECTIONS 29 & 30, T 30 N, R 6 E, M.D.B. & M.

Surveyed at the request of  
 JOE N. LEE

by  
 A.J. VANDENBERG - Reg. Civil Engineer No. 7567  
 Susanville, Calif.



SCALE: 1" = 500'



This corner found in original location and  
 monumented by duly marked brass cap of the  
 General Land Office; Marked a new witness tree as follows:  
 a 6" dia. Cedar bearing S 88°W, dist. 29'; mkd. "T 30 N R 6 E #7567"

This  $\frac{1}{4}$  corner not found after thorough search  
 and therefore considered lost.  
 Corner was reestablished and monumented by  
 $\frac{3}{4}$ " diam. iron pipe tagged "RE 7567" in rock mound and  
 witnessed as follows:  
 a 6" dia. Wh. Fir bearing N 40°W, dist. 24', mkd. "4 SC 30 RE 7567"  
 a 12" dia. S. Pine bearing S 25°E, dist. 28', mkd. "4 SC 31 RE 7567"

This corner found at original location mkd. by  
 small rock mound in which was set a  $\frac{3}{4}$ " dia.  
 iron pipe tagged "RE 7567" and witnessed as  
 follows:  
 Original bearing tree - a 8" dia. Cottonwood  
 bearing West dist. 8' mkd. "31 6 E 31"  
 New bearing trees mkd. as follows:  
 a Wh. Fir 12" dia. S 42°W dist. 40' mkd. "87 SC 31 RE 7567"  
 a Cottonwood 28" dia. S 15°W dist. 56' mkd. "87 SC 31 RE 7567"

This  $\frac{1}{4}$  corner not found.  
 Original location of this corner  
 found as mounted by rock mound  
 in which was set a  $\frac{3}{4}$ " dia. iron pipe  
 tagged "RE 7567" and witnessed by original  
 bearing trees as follows:  
 a Yellow Pine 4" dia bearing S 2°E, dist. 28', mkd. but illegible;  
 a Yellow Pine 4" dia. (false) brg N 6°W, dist. 82', mkd. but illegible;  
 No other trees near.  
 This location was used for purposes of this survey.  
 A duly marked lava stone and a duly marked  
 2" dia. iron pipe with brass cap of the General Land  
 Office was found S 85°04'W, dist. 51.70' from the original  
 location above described.

NOTES:  
 The bases of bearings of this map are  
 direct solar observations taken at the  
 southeast corner of Section 29 and at  
 the southeast corner of Section 30.

The words "Record" and "Rec." refer to  
 Government Land Office records of the  
 original government surveys.

I, A.J. VANDENBERG, hereby certify that I am a  
 Registered Civil Engineer of the State of California; that this  
 map correctly represents a survey made by me in  
 July, 1953; and that all monuments shown hereon  
 actually exist and occupy the positions indicated.

June 2, 1954  
 Date

A.J. VANDENBERG  
 Reg. Civ. Engr. 7567

I, A.J. Watson, County Surveyor of Plumas  
 County, Calif., hereby certify that I have examined  
 this map in accordance with the provisions of law.

June 9th, 1954  
 Date

A.J. WATSON, R.E. No. 2554  
 County Surveyor of Plumas County

2547  
 Filed for Record this 10 day of  
 June, 1954, at 15 minutes past 10, A.M.

*John Watson*  
 County Recorder of Plumas County

by Deputy  
 Fee: \$1.00  
 Instrument: