


SURVEYOR'S CERTIFICATE

This map correctly represents a survey made by me or
under my direction in conformance with the requirements
of the Land Surveyors Act at the request of _____
in _____, 1977



John W. Hamby
LS 2843

BASIS OF BEARING:

The East line of Parcels 3 and 4 shown as N 21° 01' 57" E
on the Parcel Map recorded in Book 2 of Parcel Maps
at Page 80. Plumas County Records

NOTE:

The purpose of this survey is to establish the East
line of the property indicated by hatch lines.

LEGEND:

- = Found 1/2" rebar with cap, RCE 11178
- = Set 3/4" IP, LS 2843
- = Found Monument as noted, set tag LS 2843
- (R & M) = Record and Measured


COUNTY SURVEYOR'S CERTIFICATE

This map has been examined for conformance with the
requirements of the Land Surveyors Act this 29th
day of August, 1977.

John W. Hamby
Plumas County Surveyor

RECORDER'S CERTIFICATE

Filed this 25th day of October, 1977 at 10:25 A.m.
in Book 4 of R.R.s at Page 138 at the
request of County Engineer
Serial No _____ Raynell Staten
Fee: \$ 5.00 County Recorder
File No _____ by Raynell Staten
deputy



RECORD OF SURVEY
for

BARBARA ROSS

THE EAST LINE OF SECTION 13, T23 N, R11 E,
M. D. B. & M
PLUMAS COUNTY, CALIFORNIA

By
John W. Hamby LS 2843
Licensed Land Surveyor
Portola, California

SHEET 1 OF 1