


SURVEYOR'S CERTIFICATE

This map was prepared by me or under my direction and is based upon a field survey in conformance with the requirements of the Land Surveyor's Act at the request of Gene LaRoe on October, 1977.



John W. Hamby
John W. Hamby L.S. 2843

COUNTY SURVEYOR'S CERTIFICATE

This map has been examined for conformance with the Land Surveyor's Act this 26th day of January, 1978.

Ray D. Fite
Plumas County Surveyor

RECORDER'S CERTIFICATE

Filed this 26th day of January, 1978, at 3:35 P.m. in Book 5 of Record of Surveys at Page 1, at the request of the County Engineer.
Fee \$5.00

File No. 5811 Raynelle Staten
Plumas County Recorder

By *Catherine Shuman*
Deputy

BASIS OF BEARING:

The center line of South Pine Street shown as S 34° 59' E on the Record of Survey filed in Book 2 of Record of Surveys at Page 95.

LEGEND:

- : Found point as noted
- : Set 3/4" Iron Pipe, LS 2843
- : Set 5/8" Rebar with cap, LS 2843
- (M): Measured
- (R): Record information

RECORD OF SURVEY FOR

GENE LA ROE

OF A PORTION OF BLOCK 7 OF PORTOLA TOWNSITE,
PORTOLA, PLUMAS COUNTY, CALIFORNIA

BY
JOHN W. HAMBY, L.S. 2843
LICENSED LAND SURVEYOR
P.O. BOX 842, 832 5571
PORTOLA, CALIFORNIA
OCT., 1977, SHEET 1 OF 1

