

NOTES FOR CORNERS FOUND AND REMONUMENTED.

- T 28 N  
 $\frac{33}{4} \frac{34}{3}$   
 T 27 N
1. FD 22"x16"x12" MARKED STONE IN STONE MOUND  
 SET 2 1/2" I.P./3" BRASS CAP - L S 4655 IN PLACE OF MKD. STONE.  
 FD REMAINS OF OLD SCRIBED POST.  
 FD ORIGINAL BEARING TREES:  
 42" Y. PINE N 54°E 80.5' (N 47°E)  
 42" Y. PINE N 63°W 17.8'  
 25" Y PINE S 15°W 49.5' (S 26°W)  
 27" Y PINE S 25°E. 42.2' (S 19 1/2°E)
- T 28 N  
 $\frac{32}{5} \frac{33}{4}$   
 T 27 N.
2. FD 18"x16"x10" MARKED STONE IN STONE MOUND.  
 SET 2 1/2" I.P./3" BRASS CAP - L S 4655 IN PLACE OF MKD. STONE.  
 CORNER FALLS IN OLD BURN  
 FD REMAINS OF ORIGINAL BEARING TREES:  
 PINE N 11 1/4°E 27.5' (29.7')  
 PINE S 49°W 16.0' (S 21°W 17.2)  
 NO TREES NEAR TO SCRIBE  
 SET STEEL FENCE POST BY CORNER.
- T 28 N  
 $\frac{32}{5}$   
 T 27 N
3. FD STONE MOUND  
 SET 2 1/2" ALUMINUM PIPE/3" CAP - L S 4655  
 FD 15" Y PINE BT NORTH 19.8'  
 FD NO TRACE OF BT TO S E  
 SCRIBED 13" Y PINE N 82°W 16.2'  
 CORNER FALLS IN OLD BURN 100' EAST OF LOGGING ROAD IN A SMALL EAST-WEST RAVINE
- T 28 N  
 $\frac{31}{6} \frac{32}{5}$   
 T 27 N
4. FD DOWN REMAINS OF 18" PINE TREE CORNER  
 FD PORTION OF SCRIBING.  
 SET 2 1/2" I.P./3" BRASS CAP - L S 4655 IN STUMP HOLE  
 FD. ORIGINAL BEARING TREES:  
 41" Y PINE N 37 1/2°E. 72.6'  
 CEDAR STUMP N.40°W 54.8'  
 FD. NO TRACE OF OTHER B.T. S  
 CORNER FALLS 75± EAST OF LOGGING ROAD.  
 SCRIBED: 6" FIR S 40°E 9.1'  
 5" W FIR N 32°W 9.0'  
 16" W FIR S.68°W. 20.7'
- 1/4 5 | 4
5. FD 23"x16"x7" MARKED STONE IN STONE MOUND  
 SET 2 1/2" ALUMINUM PIPE /3" CAP - L.S. 4655 IN PLACE OF MKD. STONE.  
 CORNER FALLS IN OLD BURN  
 SCRIBED 13" Y. PINE S 33°W 23.0'  
 19" Y PINE S 46°E 41.4'  
 SET STEEL FENCE POST BY CORNER.
- 1/4 4 | 3
6. FD 40"x30"x26" STONE - NOT MARKED - IN STONE MOUND  
 SET 2 1/2" I.P./3" BRASS CAP - L S 4655 IN PLACE OF STONE IN STONE MD  
 FD ORIGINAL BEARING TREES:  
 22" Y PINE N. 49°E 46.8' (N 44°E)  
 16" PINE SNAG BT. N 29°W 45.5' (N 38°W)  
 SCRIBED 11" D. FIR N 22°W 7.1'
- 1/4 4 | 9
7. FD 28"x18"x10" MARKED STONE  
 SET 2 1/2" I.P./3" BRASS CAP - L S 4655 IN PLACE OF MARKED STONE.  
 FD ORIGINAL BEARING TREES:  
 32" Y PINE S 58°E 29.7' (S 63°E)  
 22" CEDAR N 15°E 26.4' (N. 8°E)
- 5 | 4  
 8 | 9
8. FD STONE MOUND  
 SET 2 1/2" ALUMINUM PIPE/3" CAP L.S 4655  
 FD. 47" Y PINE BT S. 51°E. 128.0'  
 FD REMAINS OF COTTONWOOD BT. N 40°E. 114.2'  
 FD 54" Y PINE BT STUMP S 42°W 250' (213.2')  
 FD NO TRACE OF BT TO N.E.  
 SCRIBED: 16" Y. PINE N 59°E 89.3'  
 13" Y. PINE N 68°W 46.0'  
 7" Y PINE S 7°W 26.0'
- 1/4 5 | 8
9. FD 22"x18"x6" STONE - NOT MARKED & BROKEN  
 SET 2 1/2" I.P./3" BRASS CAP IN PLACE OF STONE.  
 FD 8" PINE BT. - DOWN - N 70°E 55.4'  
 NO TRACE OF B.T TO S.W.  
 SCRIBED: 4" Y PINE EAST 31.2',  
 3" Y PINE N 10°E. 32.6'
- 6 | 5  
 7 | 8
10. FD 24"x20"x3" STONE - BROKEN & NOT MARKED.  
 FOUND NO IDENTIFIABLE REMAINS OF ORIGINAL BEARING TREES.  
 STONE VERIFIED AS CORNER POSITION BY U.S.F.S. FIELD NOTES DATED 8/27/62, WHICH STATED THAT AT THAT DATE ROTTED REMAINS OF BEARING TREES DID EXIST ACCEPTED AS BEST AVAILABLE EVIDENCE.  
 SCRIBED: 12" S PINE N 80°E 11.45'  
 8" CEDAR S 32°E 18.55'  
 8" CEDAR N. 10°W. 10.50'  
 6" Y. PINE S 72°W. 12.60'  
 SET 2 1/2" ALUMINUM PIPE/3" CAP L.S. 4655 IN PLACE OF STONE.

- 1/4 8 | 9
- 9 | 10  
 16 | 15
- 1/4 9 | 16
- 1/4 16 | 15
- 16 | 15  
 21 | 22
11. FD 18"x15"x14" MARKED STONE  
 SET 2 1/2" I.P./3" BRASS CAP - L S 4655 IN PLACE OF MKD. STONE  
 FD ORIGINAL BEARING TREES:  
 16" Y PINE WEST 5.3'  
 28" Y PINE S 87°E. 19.1'  
 CORNER FALLS 50' WEST OF LOGGING ROAD
12. FD 20"x10"x8" MARKED STONE  
 SET 2 1/2" ALUMINUM PIPE/3" CAP - L S 4655  
 FD ORIGINAL BEARING TREES  
 49" Y PINE N 49°W 71.9'  
 48" Y PINE S 82°E 77.9'  
 31" Y PINE S. 30 1/2°W 102.3'  
 28" TAMARACK N. 47°E. 220.4'  
 FD 2" BRASS CAPPED I P MKD. STATE OF CALIF. DEPT OF WATER RESOURCES  
 S 64°54'35"W 7.71' IN. N-S FENCE
13. FD 14"x12"x5" STONE - NOT MARKED  
 SET 2 1/2" I.P./3" BRASS CAP - L S 4655  
 FD 33" Y PINE S 23°W 25.1' (S 21°W)  
 FD 28" Y PINE N 11°W 46.2' (N 17°W)
14. FD MARKED STONE  
 FD 2" BRASS CAPPED I P MKD. STATE OF CALIF. DEPT OF WATER RESOURCES.  
 FD 29" Y PINE BT S 52°E 26.3' (S 57°E 26.4')  
 FD 37" Y PINE - NOT SCRIBED - N 70°W 25.6'  
 FD PINE BT - ROTTEN STUMP - N 80°W 25.1'
15. FD 15"x13"x9" STONE IN STONE MOUND  
 FD 2" BRASS CAPPED I P MKD STATE OF CALIF. DEPT OF WATER RESOURCES  
 FD 32" Y PINE BT N 51°E 41.6' (40.3')  
 FD 17" Y PINE BT S 39°E 30.7' (31.7')  
 NO TRACE OF OTHER ORIG B.T. S  
 CORNER IS AT AN ANGLE POINT IN N-S FENCE.

NOTES FOR CORNERS SET

1. ORIGINAL 1/4 CORNER LOST - LOCATED BY PROPORTION  
 SET 2 1/2" I.P./3" BRASS CAP - L.S 4655 IN STONE MOUND  
 SCRIBED: 16" W FIR N 75°E 23.1'  
 21" W. FIR S 73°E 32.6'
2. SET 2 1/2" I.P./3" BRASS CAP - L.S 4655  
 SCRIBED: 18" W FIR S 87°W. 10.1'  
 18" D FIR N 86°E 10.5'  
 CORNER FALLS 75' WEST OF "WILDCAT ROAD".
3. SET 2 1/2" I.P./3" BRASS CAP - L S 4655 IN STONE MOUND. SET STEEL FENCE POST BY CORNER. CORNER IS 100± EAST OF ROAD. NO TREES NEAR.
4. SET 2 1/2" ALUMINUM PIPE/3" CAP - L S 4655  
 TAGGED: 2" Y PINE S 22°W 3.3'  
 3" Y PINE N. 40°W 19.5'  
 CORNER FALLS IN REPLANTED BURN - 100± WEST OF CREEK.
5. SET 2 1/2" ALUMINUM PIPE/3" CAP - L S 4655  
 SCRIBED: 7" CEDAR S 34°W. 12.65'  
 8" W FIR N 40°E 23.3'  
 CORNER IS 75' EAST OF ROAD
6. SET 2 1/2" ALUMINUM PIPE/3" CAP - L.S 4655  
 SCRIBED: 17" Y PINE N 52°W 18.70'  
 13" Y PINE S 26°W 28.15'
7. SET 2 1/2" I.P./3" BRASS CAP - L.S 4655  
 SCRIBED 22" Y PINE S 77°W. 125.5'  
 15" Y PINE S 88°E 94.84'  
 METAL FENCE POST & TAG BEARS N 24°E. 3.4'
8. SET 2 1/2" ALUMINUM PIPE/3" CAP - L.S. 4655  
 SCRIBED: 9" D FIR S 65°W 6.4'  
 8" Y PINE N 10°W. 29.0'
9. SET 2 1/2" ALUMINUM PIPE/3" CAP - L.S. 4655  
 SCRIBED: 14" Y PINE S 37°W. 12.4'.  
 11" Y PINE N 88°E 30.7'
10. SET 2 1/2" ALUMINUM PIPE/3" CAP - L.S 4655  
 TAGGED: 2" Y. PINE N. 62°W. 4.4'  
 PLACED K TAG ON 5"x8"x10" GRANIT BOULDER  
 S 12°E 28.60'

11. SET 2 1/2" ALUMINUM PIPE/3" CAP - L S 4655  
 SCRIBED 11" Y PINE N 39°E 125.6'  
 TAGGED 3" Y PINE S 89°E 60.0'
12. SET 2 1/2" ALUMINUM PIPE/3" CAP - L S 4655  
 SCRIBED: 6" D FIR N 72°W 15.80'  
 11" D FIR N 83°E 6.90'
13. SET 2 1/2" ALUMINUM PIPE/3" CAP - L S. 4655  
 SCRIBED: 11" Y PINE S 30°E 2.3'  
 14" Y PINE N 14°E 26.4'
14. SET 2 1/2" ALUMINUM PIPE/3" CAP - L S 4655  
 SCRIBED 7" CEDAR N 49°E. 17.6'  
 10" W FIR S 27°E 13.2'
15. SET 2 1/2" ALUMINUM PIPE/3" CAP - L S 4655  
 SCRIBED 9" W FIR S 48°E 13.1'  
 6" W FIR S 88°W. 17.7'
16. SET 2 1/2" ALUMINUM PIPE/3" CAP - L.S 4655  
 SCRIBED: 16" W. FIR N 8°W. 6.2'  
 13" W FIR N 63°E 12.8'
17. SET 2 1/2" ALUMINUM PIPE/3" CAP - L.S 4655  
 SCRIBED: 15" D FIR S 88°E 22.4'.  
 8" Y PINE N 58°W 14.9'



RECORD OF SURVEY  
 OF CERTAIN LINES IN SECTIONS  
 4, 5, 8, 9, AND 16 T. 27N R. 12E MDM.  
 PLUMAS COUNTY CALIFORNIA  
 FOR  
 ARCHIE D. WALKER JR  
 PLUMAS NATIONAL FOREST  
 DECEMBER 1979 SCALE: 1"=1000'  
 LOUIS A VONDERSCHEER - L S 4655