

**TSN R9E**  
N 1/4 S 28  
LS 3634  
1988

33 SET standard Forest Service monument in rock mound from which bears a:  
10" White Fir S 49° 07' W 11.6  
8" Black Oak N 47° 58' W 17.0

**TSN R9E**  
N 1/4 S 28  
LS 3634  
1988

34 SET standard Forest Service monument in rock mound from which bears a:  
12" Black Oak S 71° 06' E 10.7  
10" White Fir S 44° 07' W 18.0  
2" x 2" hub and tack South 3.96

35 FOUND standard BLM monument (1967) set in rock mound from which bears a:  
21" Fir S 75° 43' W 40.5  
36" Yellow Pine N 71° 48' E 14.2  
  
(28" Yellow Pine N 71° E 14.5)  
(14" Douglas Fir S 77° W 40.6) (G)

**TSN R9E**  
C 1/4 S 28  
LS 3634  
1988

36 SET standard Forest Service monument in rock mound from which bears a:  
12" Cedar N 89° E 14.2  
7" Fir S 15° E 6.8  
2" x 2" wooden hub and tack S 56° 00' W 0.48

37 FOUND standard BLM monument (1967) set in rock mound (R<sub>3</sub>) from which bears a:  
10" Fir S 39° 36' W 17.2  
9" Yellow Pine S 17° 47' E 10.0  
  
(9" Fir S 39-1/2° W 17.2 )  
(9" Yellow Pine S 18° E 9.9) (G)

**TSN R9E**  
S 1/4  
30 + 29  
LS 3634  
1988

38 SET standard Forest Service monument in rock mound from which bears a:  
6" Ponderosa Pine N 19° 40' E 15.9  
9" White Fir S 37° E 15.0  
A small rock mound N 68° E 9.0

**TSN R9E**  
SW 1/4 S 29  
LS 3634  
1988

39 SET standard Forest Service monument in rock mound from which bears a:  
8" Black Oak N 82° 31' E 17.4  
8" Red Fir S 9° 01' W 29.3

**TSN R9E**  
SW 1/4 S 29  
LS 3634  
1988

40 SET standard Forest Service monument in rock mound from which bears a:  
6" Douglas Fir S 88° 12' W 24.0  
8" Douglas Fir S 12° 29' W 24.4

**TSN R9E**  
SW 1/4 S 29  
LS 3634  
1988

41 SET standard Forest Service monument in rock mound from which bears a:  
8" Douglas Fir S 1° 41' W 12.1  
6" Douglas Fir N 37° 14' W 31.8

**TSN R9E**  
SW 1/4 S 29  
LS 3634  
1988

42 SET standard Forest Service monument in rock mound from which bears a:  
5" Douglas Fir N 40° 01' E 13.3  
5" Douglas Fir N 54° 03' W 12.7

**TSN R9E**  
SW 1/4 S 29  
LS 3634  
1988

43 SET standard Forest Service monument in rock mound from which bears a:  
10" Douglas Fir S 10° 32' W 31.9  
8" Black Oak S 74° 02' E 18.0

44 FOUND a 3/4" iron pipe LS 3297 as per (R<sub>3</sub>) (called 1" iron pipe)  
N 77° 30' 08" W 0.21 from calc position

45 FOUND standard BLM monument (1967) set in rock mound from which bears a:  
15" Twin Black Oak N 20° 09' E 30.4  
9" Yellow Pine S 26° 28' E 5.7  
12" White Fir S 71° 06' W 21.2  
8" Black Oak N 72° 12' W 33.5  
  
(14" Black Oak N 21° E 31.0 )  
( 7" Black Oak N 71° W 33.3 )  
( 8" White Fir S 73° W 21.4 ) (G)  
( 8" Yellow Pine S 24° E 5.3 )

46 FOUND standard BLM monument (1967) set in rock mound from which bears a:  
14" Sugar Pine S 82° 44' W 16.1  
16" Fir N 70° 29' E 28.1  
  
(15" Douglas Fir N 70-1/2° E 28.1)  
(11" Sugar Pine S 84° W 16.2 ) (G)

47 FOUND standard BLM monument (1967) set in rock mound as per (R<sub>3</sub>) and (R<sub>4</sub>) from which bears a:  
6" Sugar Pine S 36° 49' W 17.1  
8" Ponderosa Pine N 23° 21' W 22.6  
8" Cedar N 50° 40' E 9.4  
14" Ponderosa Pine S 34° 55' E 9.5  
See NOTE "A" hereon

48 FOUND standard BLM monument (1967) set in rock mound as per (R<sub>3</sub>) from which bears a:  
27" Ponderosa Pine N 34° 47' W 19.9  
20" Sugar Pine S 63° 44' E 40.6  
  
(22" Yellow Pine N 36° W 19.8)  
(16" Sugar Pine S 65° E 40.6) (G)

49 FOUND 20" Black Oak with reference corner, a standard BLM monument marked 9 feet to corner as per (R<sub>3</sub>) (R<sub>6</sub>) S 46 18' 39" W 9.00  
38" Pine Snag S 46° 50' W 17.6  
22" Cedar N 17° 42' W 39.0  
13" Douglas Fir N 38° 27' E 52.3  
14" Sugar Pine S 78° 38' E 36.0  
  
( 5" Fir N 38° E 52.1 )  
(14" Cedar N 18° W 38.9 )  
( 7" Sugar Pine S 78° E 36.3 ) (G)  
(29" Yellow Pine S 44° W 17.2 )  
(Reference monument S 45° W 9.0)

50 FOUND standard Forest Service monument in rock mound as per (R<sub>6</sub>) from which bears a:  
12" Black Oak S 19° 47' E 49.4  
15" Black Oak N 84° W 13.7  
  
(15" Black Oak N 84° W 13.7)  
(12" Black Oak S 19° E 49.4) (R<sub>6</sub>)

51 FOUND standard BLM monument set in rock mound from which bears a:  
9" Black Oak N 11° 08' W 64.4  
4" Black Oak N 49° 25' E 7.1  
10" Sugar Pine S 51° 05' E 47.6  
8" Cedar S 27° 33' W 18.4  
  
(4-1/2" Black Oak N 49° E 7.2)  
(10" Sugar Pine S 51° E 47.6 )  
( 8" Cedar S 28° W 17.8 ) (R<sub>6</sub>)  
( 7" Black Oak N 12° W 64.5 )  
  
(4" Black Oak N 49-1/2° E 7.3)  
(6" Sugar Pine S 51° E 47.5 )  
(4" Cedar S 28-1/2° W 18.5 ) (G)  
(6" Black Oak N 12° W 64.0 )

**TSN R9E**  
N 1/4 S 28  
LS 3634  
1988

52 SET standard Forest Service monument in rock mound in old roadway intersection from which bears a:  
15" Douglas Fir N 68° 29' W 49.3  
6" Yellow Pine N 19° 50' E 54.2  
1" Iron Pipe LS 3297 (R<sub>3</sub>) S 31 51' E 1.00

53 FOUND 1" iron pipe LS 3297 as per (R<sub>3</sub>), 4-P/M-25, 0.42 South of line.

54 FOUND 1/2" iron pipe LS 3297 at Northwest corner Parcel 4 of 4-P/M-25, 0.33 South of line.

55 FOUND 1/2" rebar RCE 11173 (R<sub>5</sub>) S 74° 38' 35" E 3.07 from calc position of N-N 1/64 corner

**TSN R9E**  
N 1/4 S 28  
LS 3634  
1988

56 SET standard Forest Service monument in rock mound from which bears a:  
8" Black Oak N 71° 10' W 41.1  
11" Ponderosa Pine N 3° 26' W 59.9  
1" open iron pipe (R<sub>3</sub>) and 4-R/S-25 at fence corner, S 11° 43' E 0.31

**TSN R9E**  
S 1/4 S 28  
LS 3634  
1988

57 SET standard Forest Service monument in rock mound from which bears a:  
12" Douglas Fir S 62° 38' E 53.4  
19" Douglas Fir S 0° 05' E 47.2  
A rock mound S 12° 30' E 28.9

58 FOUND 1" iron pipe LS 3297 as per (R<sub>3</sub>), 0.27 South of line.

**TSN R9E**  
C 1/4 S 28  
LS 3634  
1988

59 SET standard Forest Service monument in rock mound from which bears a:  
10" Ponderosa Pine N 8° 10' W 59.3  
16" Ponderosa Pine N 72° 45' W 41.4  
1" iron pipe LS 3297 (R<sub>3</sub>) S 88° 37' W 6.25

60 FOUND standard BLM monument (1967) set in rock mound from which bears a:  
  
24" Cedar S 53° 01' E 52.6  
8" Black Oak N 46° 52' W 44.0  
  
( 6" Black Oak N 46-1/2° W 44.2 )  
(20" Cedar S 53° E 52.8 ) (G)

**TSN R9E**  
SE 1/4 S 28  
LS 3634  
1988

61 SET standard Forest Service monument in rock mound from which bears a:  
11" Red Fir S 17° E 2.3  
8" Cedar S 86° E 10.1  
1" iron pipe LS 3297 (R<sub>3</sub>) S 42° 16' E 16.39  
1/2" rebar and aluminum cap LS 2843 (R<sub>4</sub>) S 51° 00' E 32.22

**TSN R9E**  
S 1/4 S 28  
LS 3634  
1988

62 SET standard Forest Service monument in rock mound from which bears a:  
8" Red Fir S 74° 29' E 44.8  
6" Black Oak S 18° 11' W 37.9  
1" iron pipe LS 3297 (R<sub>3</sub>) N 87° 53' E 0.73

63 FOUND 1" iron pipe LS 3297 as per (R<sub>3</sub>), 0.16 south of line.

**TSN R9E**  
S 1/4 S 28  
LS 3634  
1988

64 SET standard Forest Service monument by single proportionment in rock mound from which bears a:  
10" White Fir S 23° 03' W 30.0  
13" Red Fir N 36° 39' W 28.8  
1/2" rebar with aluminum cap LS 2843 (R<sub>4</sub>) N 74° 06' W 0.16, removed to set new corner and placed along side of new monument  
Small mound of rocks N 52° 43' E 8.2  
No evidence of original corner or Bearing  
Trees as per (G) found

NOTE "A"

47 CONTINUED  
( 5" Sugar Pine S 36° W 17.49 )  
( 7" Yellow Pine N 22-1/2° W 22.44 )  
( 6" Cedar N 52-1/2° E 9.57 )  
(11" Yellow Pine S 34° E 9.57)

**TSN R9E**  
S 1/4 S 28  
LS 3634  
1988

65 SET standard Forest Service monument in rock mound from which bears a:  
6" Ponderosa Pine N 87° 02' E 49.7  
12" Ponderosa Pine N 2° 15' E 27.4  
1/2" rebar with aluminum cap LS 2843 (R<sub>4</sub>) N 35° 32' E 0.18 removed and placed along side of new monument

66 FOUND 5/8" rebar with aluminum cap LS 2843 (R<sub>4</sub>) at delapidated fence corner marking North corner Governor Mineral Survey

67 FOUND standard BLM monument (1967) set in rock mound as per (R<sub>3</sub>) (R<sub>4</sub>) from which bears a:  
10" Black Oak with rotted interior N 22° 40' W 38.5  
10" Cedar N 50° 55' E 58.2  
10" Fir S 4° 41' E 30.0  
10" Fir S 56° 57' W 33.2  
  
(12" Cedar N 51° E 58.1 )  
(10" Black Oak N 22-1/2° W 37.6 )  
( 9" Fir S 56° W 33.0 ) (G)  
(10" Fir S 5° E 30.0 )

68 FOUND standard BLM monument set in rock mound from which bears a:  
10" Sugar Pine S 48° W 13.9 (Fallen)  
8" Douglas Fir N 35° 51' W 14.3  
  
(6" Fir N 35° W 14.2 )  
(9" Sugar Pine S 46° W 13.9) (G)

69 FOUND standard BLM monument set in rock mound from which bears a:  
9" Ponderosa Pine N 85° 13' E 5.0  
25" Ponderosa Pine S 19° 38' E 28.6  
15" Douglas Fir S 42° 39' W 19.0  
11" Sugar Pine N 26° 05' W 6.4  
  
(24" Yellow Pine S 19-1/2° E 28.4)  
( 9" Yellow Pine N 87° E 5.0 )  
( 9" Sugar Pine N 26° W 6.3 ) (G)  
(12" Douglas Fir S 41° W 19.1 )

**TSN R9E**  
N 1/4 S 28  
LS 3634  
1988

70 SET standard Forest Service monument in rock mound from which bears a:  
7" Sugar Pine S 54° 56' W 4.9  
10" Red Fir N 2° 45' W 9.5  
1/2" rebar with aluminum cap LS 2843 S 39° 56' E 0.98

**RECORD OF SURVEY**  
**FOR**  
**U.S.D.A. - PLUMAS NATIONAL FOREST**  
**'BUTTERFLY CADASTRAL SURVEY'**

Being portions of Sections 17, 20, 27, 28, 29 and 33  
T. 25 N. - R. 9 E. - M.D.M.

PLUMAS CO., CA  
JUNE, 1988  
**LIPPINCOTT SURVEYING**  
1007 BILLE ROAD - P.O. BOX 671 - PARADISE, CA 95967  
Ph. 916/ 877-4300