

Corner Notes

- ① Section Corner to Sections 4-5-32-33
Found rock mound 350 ft. west of dirt road and 49-in. p. pine N 33° 30' E, 389.5 ft. (record N 33° E, 580 lks.). Set ACAP, and scribed and tagged: 1) 18-in. p. pine S 74° 18' E, 25.2 ft.; 2) 12-in. p. pine S 0° 30' E, 39.3 ft.; 3) 19-in. p. pine S 67° 12' W, 41.8 ft.
- ② Quarter Corner between Sections 33-4
Found rock mound 250 ft. east of a dirt road on a flat, and a down and dead pine with scribing S 12° 04' W, 38.1 ft. (record S 10° W, 56 lks.). Set ACAP, and scribed and tagged: 1) 20-in. p. pine N 83° 22' W, 75.8 ft.; 2) 23-in. p. pine S 45° 43' W, 53.6 ft.
- ③ E 1/4 Corner between Sections 33-4
Corner falls in an area of large, buried rocks on a southwest slope. Set ACAP as reference point S 45° 30' E, 9.84 ft. from corner position. Scribed and tagged from corner position: 1) 23-in. p. pine S 37° 37' W, 65.0 ft.
- ④ Section Corner to Sections 3-4-33-34
Found rock mound on rocky southwest slope, and the following original bearing trees: 1) pine snag with scribing S 60° 19' E, 30.7 ft. (record S 57° E, 44 lks.) and 2) 24-in. p. pine in good condition with closed face N 39° E, 51.8 ft. (record N 41° E, 127 lks.). Scribed and tagged: 1) 11-in. p. pine S 32° 41' E, 73.1 ft.; 2) 32-in. p. pine S 24° 58' W, 42.6 ft.
- ⑤ N 1/4 between Sections 5-4
Set ACAP on gentle west slope, and scribed and tagged: 1) 12-in. p. pine N 23° E, 11.3 ft.; 2) 8-in. p. pine N 54° W, 5.3 ft. Found LS 3336 3/4-in. iron pipe S 27° 46' E, 17.1 ft., but did not accept this position, as the BLM 1/4 corner between sections 5-4 was not used by LS 3336.
- ⑥ NW 1/4 Corner, Section 4
Set ACAP on gentle north slope some 100 ft. west of a dirt road. Scribed and tagged: 1) 11-in. p. pine S 28° 36' W, 41.1 ft.; 2) 13-in. p. pine S 27° 49' W, 28.8 ft. Found LS 3336 3/4-in. iron pipe S 17° 15' E, 13.7 ft., but did not accept this position, as the BLM 1/4 corner between sections 5-4 was not used by LS 3336.
- ⑦ Quarter Corner between Sections 5-4
Found BLM BCIP on brushy west slope from which bears: 1) 28-in. juniper S 76° W, 11.7 ft. (record S 80° W, 18 lks.); 2) 22-in. juniper S 69° 47' E, 54.3 ft. (record S 75° E, 88 lks.)
- ⑧ SW 1/4 Corner, Section 4
Set ACAP on west side of skid road. Scribed and tagged: 1) 23-in. w. fir S 75° 26' W, 17.6 ft.; 2) 17-in. p. pine S 01° 53' W, 35.8 ft.
- ⑨ SE 1/4 Corner, Section 4
Set ACAP on rocky south slope some 150 ft. south of a prominent rock knob just east of the 1/4 line. Scribed and tagged: 1) 18-in. p. pine S 7° 44' E, 51.9 ft.; 2) 14-in. p. pine N 70° 03' E, 32.8 ft.
- ⑩ Quarter Corner between Sections 4-3
Set ACAP on open south slope 140 ft. south of a dirt road, at proportionate distance between ridge call to the north and creek call to the south on a line between section corners to the north and south. Found 3/4-in. iron pipe per 3 PM 48 S 31° 12' E, 23.22 ft. that I did not accept as 1/4 corner because it was not on line between section corners, nor at the proper position from the creek and ridge calls. Scribed and tagged: 1) 10-in. p. pine S 37° 23' E, 30.4 ft.; 2) 14-in. p. pine S 17° 21' W, 58.1 ft.
- ⑪ SW 1/4 Corner, Section 4
Set ACAP on a flat, and scribed and tagged: 1) 15-in. p. pine S 62° 52' W, 27.5 ft.; 2) 22-in. p. pine N 29° 35' W, 8.2 ft.
- ⑫ Section Corner to Sections 5-4-9-8
Found rock mound with 2-in. D.M.R. and bearing trees per Book 3 of Parcel Maps, Page 49.
- ⑬ C 3/4 Corner, Section 4
Set ACAP 100 ft. east of creek in a large open area. Scribed and tagged: 1) 17-in. p. pine N 36° 44' E, 105.5 ft.; 2) 20-in. pine S 85° 10' W, 147.4 ft. Found LS 3336 iron pipe S 76° 05' E, 26.6 ft.; did not accept as both west and east 1/4 corners are in error in 3 PM 48.
- ⑭ Quarter Corner between Sections 4-9
Found and accepted ACAP 30-ft. west of dirt road by LS 5623 and the following BT's: 1) 17-in. p. pine N 35° 42' W, 27.7 ft.; 2) 16-in. p. pine S 66° 48' W, 29.6 ft.
- ⑮ E 1/4 Corner between Sections 4-9
Found 1/2-in. pipe with 2-in. cap properly stamped by LS 5623.
- ⑯ Section Corner to Sections 3-4-9-10
Found and accepted BLM BCIP and the following BT's: 1) 29-in. p. pine N 30° E, 84.5 ft. (record N 26° E, 133 lks.); 2) pine stump S 35° E, 21.1 ft. (record S 30° E, 32 lks.); 3) 35-in. p. pine N 46° W, 114.2 ft. with overgrown face (record N 50° W, 170 lks.); 4) 10-in. p. pine S 34° E, 57.4 ft.
- ⑰ W 1/4 Corner between Sections 3-10
Set ACAP on south slope in a stand of small pine. Scribed and tagged: 1) 12-in. p. pine N 38° 05' W, 8.3 ft.; 2) 10-in. p. pine N 56° 48' E, 15.0 ft.
- ⑱ Quarter Corner between Sections 3-10
Found BLM BCIP 280 ft. north of a dirt road properly stamped, and dated 1973. Original BT's are: 1) pine stump S 31° E, 103.6 ft. (record S 31° E, 153 lks.); 2) 30-in. pine snag N 32° W, 85.1 ft. (record N 32° W, 137 lks.). New BLM BT's are: 1) 12-in. p. pine N 71° E, 25.7 ft.; 2) 16-in. p. pine S 65° W, 31.0 ft.
- ⑲ N 1/4 Corner between Sections 9-10
Found and accepted 1/2-in. aluminum rod with properly stamped aluminum cap by LS 5623. Scribed the following BT's: 1) 20-in. p. pine S 82° W, 14.0 ft.; 2) 26-in. p. pine S 45° 30' E, 52.2 ft.
- ⑳ NW 1/4 Corner, Section 10
Set ACAP on open west slope. Scribed and tagged: 1) 11-in. p. pine N 80° 36' W, 32.3 ft.; 2) 16-in. white fir S 5° 02' W, 137.9 ft.
- ㉑ Quarter Corner between Sections 9-10
Found and accepted ACAP by LS 5623 in large rock mound some 50 ft. west of a dirt road.
- ㉒ C 1/4 Corner, Section 10
Set ACAP on open west slope 150 ft. west of a rocky ridge. Scribed and tagged: 1) 15-in. white fir S 50° 53' E, 8.9 ft.; 2) 8-in. white fir N 10° 33' W, 31.7 ft. Found 1/2-in. rebar S 6° 05' E, 26.4 ft. per 5 R/S 130 by LS 2843. Did not accept any corner position per 5 R/S 130, as the 1/4 corner position to Sections 10-11 is reported in error on said map.
- ㉓ Quarter Corner between Sections 10-11
Found BLM BCIP some 50 ft. north of a dirt road, properly stamped and dated 1973. Found the original BT's as follows: 1) 38-in. fir snag with closed face S 80° 48' W, 15.5 ft. (record S 71° W, 23 lks.); 2) 16-in. p. pine N 79° 25' E, 15.6 ft. (record N 76° E, 24 lks.), and a new BLM 10-in. white fir BT N 29° 51' E, 41.3 ft.
- ㉔ SE 1/4 Corner, Section 10
Set ACAP on northwest side of a large rock, and scribed and tagged: 1) 10-in. white fir S 40° 50' E, 34.5 ft.; 2) 19-in. p. pine N 8° 36' E, 70.8 ft. Found 1/2-in. rebar per 5 R/S 130 S 41° 29' E, 30.8 ft. that I did not accept. (See corner note #22.)
- ㉕ S 1/4 Corner between Sections 10-11
Set ACAP on rocky west slope. Scribed and tagged: 1) 11-in. p. pine S 4° 48' E, 29.6 ft.; (2) 22-in. p. pine N 60° 53' E, 54.5 ft. Found 1/2-in. rebar per 5 R/S 130 S 52° 11' E, 49.7 ft. that I did not accept. (See corner note #22.)

- ㉖ Quarter Corner between Sections 10-15
Found BLM BCIP properly stamped, and dated 1973. Original bearing trees found are: 1) 24-in. p. pine S 5° 50' E, 27.9 ft. (record South, 40 lks.); 2) 34-in. p. pine N 9° 34' E, 27.7 ft. (record N 40° E, 44 lks.).
- ㉗ E 1/4 Corner between Sections 10-15
Set ACAP next to 1/2-in. rebar per 5 R/S 130. Scribed and tagged: 1) 9-in. p. pine N 49° E, 10.1 ft.; 2) 8-in. p. pine N 33° W, 17.3 ft.
- ㉘ Section Corner to Section 10-11-14-15
Found BLM BCIP properly stamped, and dated 1973. Original bearing trees found are: 1) 30-in. down and dead pine S 36° E, 57.4 ft.; 2) 36-in. p. pine S 24° W, 60.0 ft. with scribing visible; 3) 21-in. p. pine down and dead with scribing N 32° W, 73.3 ft. (record N 37° W, 109 lks.). New BLM BT's found are: 1) 12-in. white fir S 78° E, 7.9 ft.; 2) 8-in. p. pine N 20° E, 14.4 ft.

Record of Survey
for
U.S. Department of Agriculture
Forest Service
East Side Cadastral Survey
Sections 4, 10, T24N-R16E, M.D.M.
in the Unincorporated Area of Plumas County
R. D. Hunt Surveying & Forestry
Arcata, California
November 1988
Sheet 2 of 2