**BASIS OF BEARING**

The center line of South Second Street, shown as S 28° 40' 41"E on 6 RS 35

**LEGEND**

● = Found 1/2" capped rebar, LS 2843, per 6 RS 35

R = Record information per 6 RS 35


M = Measured

**NOTES**

This Record of Survey was prepared to reflect a Lot Line Adjustment approved by the City of Portola on 3 April, 1989. Said approval also included merging of lots 13, 14, 15 & 16 of Block 2.

**SURVEYOR'S STATEMENT**

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors Act at the request of RICHARD JOY on APRIL 3, 1989.



*John W. Hamby*  
John W. Hamby LS 2843

**COUNTY SURVEYOR'S STATEMENT**

This map has been examined in accordance with Section 8766 of the Land Surveyors Act this 31st day of MAY, 1989.

*Lawrence J. Brock*  
Lawrence J. Brock RCE 13528

**COUNTY RECORDER'S STATEMENT**

Filed this 31st day of MAY, 1989, at 2:30 p.m. in Book 8 of Record of Surveys at Page 72 at the request of the County Engineer.

Fee 5.00  
File No. 3148

*Ilia Diggs*  
Ilia Diggs  
Plumas County Recorder

*Debra P. de Valle*  
Debra P. de Valle  
Deputy

OF A PORTION OF BLOCK 2 OF THE EASTERN ADDITION  
TO PORTOLA TOWNSITE, PLUMAS COUNTY, CALIFORNIA

A PORTION OF SECTION 36, T 23 N R 3 E, M.D.B. & M.

MAY, 1989

HAMBY SURVEYING INC.  
Portola, California  
P.O. Box 1209  
(916) 832-5571

SHEET 1 OF 1