

<p>T24N R6E S33 S5 S4 CORNER NO. 1</p> <p>T23N R6E 1938 FD. A 2" IRON PIPE WITH A 2 1/2" GLO BRASS CAP IN A MOUND OF STONE. ACCESSORIES NOT TIED</p> <p>REC. A 12" BLACK OAK BEARS N53 1/2"E, 42.9' (GLO 1938) REC. A 12" BLACK OAK BEARS S32"E, 40.9'(GLO 1938) REC. AN 8" BLACK OAK BEARS S51"W, 10.6'(GLO 1938) REC. A 10" BLACK OAK BEARS N35"W, 50.2'(GLO 1938) REC. A 10" CEDAR BEARS S46 1/2"E, 114.2'(GLO 1938)</p>	<p>T23N R6E S9 1/4 S16 CORNER NO. 8</p> <p>SET STD DTI MONUMENT, NO MOUND OF STONE. CORNER FALLS ON A STEEP SOUTHWEST SLOPE IN DENSE BRUSH, 300'± WEST OF AN OLD SKID ROAD.</p> <p>AN 8" BLACK OAK BEARS S58 3/4"E, 16.9'-SBT "1/4 S16 BT" A 9" BLACK OAK BEARS S5 3/4"W, 5.9'-SBT "1/4 S9 BT"</p>	<p>CORNER NOTES</p> <p>H.B. = HEALED BLAZE V.S. = VISIBLE SCRIBING S.B.T. = SCRIBED AS A BEARING TREE STD. DTI MON. = 3 1/2" ALUM. CAP ON A 2" ALUMINUM PIPE</p>	<p>T23N R6E S21 S22 S28 S27 CORNER NO. 19</p> <p>FD. AN ALUMINUM MONUMENT WITH A 2 1/2" CAP IN A MOUND OF STONE. CORNER FALLS 60'± WEST OF A DRAW ON A GENTLE SOUTH SLOPE.</p> <p>FD. A 39" CEDAR BEARS S19"W, 17.9'-HB REC. A 10" CEDAR BEARS S05"W, 17.8'(GLO 1875) FD. ROTTED REMAINS OF A FIR, N30"E, 16.5' REC. A 36" FIR BEARS N30"E, 23.1'(GLO 1875) *FD. A 9" WHITE FIR BEARS N36"W, 13.9'-VS *FD. AN 8" RED FIR BEARS N17"E, 20.9'-HB *FD. A 15" WHITE FIR BEARS S81"E, 19.8'-VS</p> <p>*TAGGED AND SCRIBED FOR BEARING TREES BUT NOT OF RECORD.</p>
<p>T24N R6E S34 S4 S3 CORNER NO. 2</p> <p>T23N R6E 1938 FD. A 2" IRON PIPE WITH A 2 1/2" BRASS CAP IN A MOUND OF STONE. CORNER FALLS ON A STEEP SOUTH SLOPE IN DENSE BRUSH, 340'± EAST AND 250'± NORTH OF GRIZZLY CREEK.</p> <p>FD. A 28" DEAD AND DOWN YELLOW PINE SNAG BEARS S64"E, 7.9'-VS REC. A 30" YELLOW PINE BEARS S64"E, 7.9'(GLO 1938) FD. A 50" YELLOW PINE BEARS S36"E, 13.2'-HB REC. A 40" YELLOW PINE BEARS S38"E, 13.2'(GLO 1938) FD. A 55" YELLOW PINE BEARS S12 1/2"W, 120.1'-HB REC. A 40" YELLOW PINE BEARS S12 1/2"W, 120.1'(GLO 1938)</p>	<p>T23N R6E S9 S10 S16 S15 CORNER NO. 9</p> <p>SET STD DTI MONUMENT AT DOUBLE PROPORTION POSITION, NO MOUND OF STONE. CORNER FALLS ON A GENTLE EAST SLOPE IN A PLANTATION IN VERY DENSE BRUSH.</p> <p>A 4" YELLOW PINE BEARS N16 1/2"E, 102.0'-SBT "T23N R6E S10 BT" A 5" YELLOW PINE BEARS S84 1/4"W, 14.0'-SBT "T23N R6E S16 BT" A 5" YELLOW PINE BEARS N60"W, 13.5'-SBT "T23N R6E S9 BT" A 6" YELLOW PINE BEARS S41 1/2"E, 32.6'-SBT "T23N R6E S15 BT"</p>	<p>T23N R6E 1/4 S16 S15 S15 CORNER NO. 13</p> <p>SET STD DTI MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A WEST SLOPE. FD. A ROTTED 60" SUGAR PINE STUMP BEARS S85"E, 26.4' TAGGED BY JOE EDGERTON IN 1976. USFS CORNER CARD INDICATES VISIBLE SCRIBING IN 1976.</p> <p>AN 18" WHITE FIR BEARS S69"E, 19.8'-SBT "1/4 S15 BT" A 12" WHITE FIR BEARS N26"E, 25.7'-SBT "1/4 S16 BT"</p>	<p>T23N R6E S17 S16 S20 S21 CORNER NO. 14</p> <p>FD. A 3 1/4" USFS CAP ON A 5/8" ROD IN A MOUND OF STONE.</p> <p>LS 5623 1991 ACCESSORIES NOT TIED</p>
<p>T23N R5E R6E S12 S7 S13 S18 CORNER NO. 6</p> <p>1938 FD. A 2" IRON PIPE WITH A 2 1/2" GLO BRASS CAP IN A MOUND OF STONE. ACCESSORIES NOT TIED</p> <p>REC. AN 8" BLACK OAK BEARS N36"E, 9.2'(GLO 1938) REC. A 10" WHITE OAK BEARS S71"E, 37.6'(GLO 1938) REC. AN 8" BLACK OAK BEARS N86"W, 33.0'(GLO 1938) REC. A 6" RED FIR BEARS N65"W, 32.3'(GLO 1938)</p>	<p>T23N R6E S10 S11 S15 S14 CORNER NO. 11</p> <p>SET STD DTI MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A STEEP SOUTHEAST SLOPE IN DENSE BRUSH, 120'± WEST OF A DRAW SLOPING SOUTH- EAST.</p> <p>FD. A DECAYED PINE STUMP BEARS S85"W, 59.4'-VS REC. A 36" SUGAR PINE BEARS S85"W, 59.4' (GLO 1875)</p> <p>NO NEW BT'S TAKEN</p>	<p>T23N R6E 1/4 S16 S21 S21 CORNER NO. 15</p> <p>SET STD DTI MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A STEEP SOUTHEAST SLOPE IN DENSE BRUSH, 120'± WEST OF A DRAW SLOPING SOUTH- EAST.</p> <p>A 5" WHITE FIR BEARS S39"W, 17.4'-SBT "X BT" A 9" BLACK OAK BEARS N10"W, 4.2'-SBT "1/4 S16 BT"</p>	<p>T23N R6E S16 S15 S21 S22 CORNER NO. 16</p> <p>SET STD DTI MONUMENT, NO MOUND OF STONE. CORNER FALLS ON A GENTLE SOUTH-SOUTHEAST SLOPE IN SCATTERED FIR AND PINE WITH DENSE BRUSH.</p> <p>A 24" WHITE FIR BEARS S41"E, 27.3'-SBT "T32N R6E S22 BT" A 10" WHITE FIR BEARS N24"E, 31.0'-SBT "T32N R6E S21 BT"</p>
<p>CORNER NO. 7</p> <p>DOUBLE PROPORTION POSITION FOR THE NORTHWEST CORNER OF SECTION 16. NOT SET. CORNER FALLS ON AN EXTREMELY STEEP, HEAVILY BRUSH COVERED NORTHWEST SLOPE.</p>	<p>CORNER NO. 12</p> <p>SINGLE PROPORTION POSITION FOR THE WEST QUARTER CORNER OF SECTION 16 FALLS ON A VERY STEEP AND DANGEROUS SOUTHWEST SLOPE. NOT SET.</p>	<p>T23N R6E 1/4 S16 S15 S16 CORNER NO. 20</p> <p>SET STD DTI MONUMENT IN A LARGE MOUND OF STONE ON THE WEST LINE OF SECTION 16, 900.00' NORTHERLY OF THE WEST QUARTER CORNER FOR WITNESS CORNER. WITNESS CORNER FALLS ON A SOUTH-SOUTHWEST SLOPE, 20'± SOUTH OF AND 10' BELOW THE TOP OF A RIDGE BEARING N70"E.</p> <p>AN 11" LIVE OAK BEARS WEST, 12.2'-SBT "X BT" A 9" LIVE OAK BEARS N5"E, 10.1'-SBT "X BT"</p>	<p>T23N R6E 1/4 S15 S22 CORNER NO. 17</p> <p>SET STD DTI MONUMENT IN A MOUND OF STONE.</p> <p>FD. A FIR SNAG BEARS NORTH 21.8' REC. A 66" RED FIR SNAG BEARS NORTH, 21.8' (USFS COR. REC #N-15) REC. A 48" RED FIR BEARS DUE NORTH, 21.8' (GLO 1875)</p>
<p>T23N R6E 485' WT COR S8 S9 S17 S16 LS 3966 1994 CORNER NO. 21</p> <p>SET STD DTI MONUMENT IN A MOUND OF STONE ON THE NORTH LINE OF SECTION 16, 485.00' EASTERLY OF THE NORTHWEST CORNER FOR WITNESS CORNER. WITNESS FALLS ON A SMALL RIDGE SLOPING N10"W, IN DENSE BRUSH.</p> <p>A 5" RED FIR BEARS S62"E, 20.1' CUT "X" IN BARK - NO SCRIBING A 6" DOUGLAS FIR BEARS N5"E, 23.1' CUT "X" IN BARK - NO SCRIBING</p>	<p>900' WT COR LS 3966 1994 CORNER NO. 21</p> <p>SET STD DTI MONUMENT IN A MOUND OF STONE ON THE NORTH LINE OF SECTION 16, 900.00' NORTHERLY OF THE WEST QUARTER CORNER FOR WITNESS CORNER. WITNESS CORNER FALLS ON A SOUTH-SOUTHWEST SLOPE, 20'± SOUTH OF AND 10' BELOW THE TOP OF A RIDGE BEARING N70"E.</p> <p>AN 11" LIVE OAK BEARS WEST, 12.2'-SBT "X BT" A 9" LIVE OAK BEARS N5"E, 10.1'-SBT "X BT"</p>	<p>RECORD OF SURVEY FOR SOPER WHEELER CO. "DUFFEY DOME" IN SECTIONS 15, 16, 21 AND 22 T 23 N, R 6 E, MDM IN THE UNINCORPORATED AREA OF PLUMAS COUNTY, STATE OF CALIFORNIA</p> <p>DEL TERRA INC. SURVEYING P.O. BOX 4632 REDDING, CA 96099 PHONE (916) 241-8050</p> <p>OCTOBER, 1994 SHEET: 2 OF 2</p>	<p>DUFFEY SH72</p>