


NOTE:  
This Record of Survey was prepared to reflect a Lot Line Adjustment  
for which a resolution is Recorded in Book LS 284 of Official Records  
at page 566.




#### LEGEND

- FOUND 3/4" IP tagged LS 2843 per 8 PM 32
- FOUND Aluminum Cap stamped LS 2843
- SET 5/8" Rebar with Aluminum Cap LS 2843
- Nothing found or set
- (R1) RECORD per 8 PM 32

95057

#### SURVEYOR'S STATEMENT

This map correctly represents a survey made by me or under my direction  
in conformance with the requirements of the Land Surveyors' Act at the  
request of Rick Joy and Bill Pearson in October, 1995.



John W. Hamby  
John W. Hamby LS 2843

#### COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the Land  
Surveyor's Act and is found to be correct.  
2nd day of January, 1996.



R. Tom Hunter

R. Tom Hunter RCE 30515  
PLUMAS COUNTY SURVEYOR  
License Expiration Date 3/31/96

#### RECORDER'S STATEMENT

Filed this 2nd day of January, 1996 at 1:51 P.M. in  
Book 10 of Record of Surveys, at page 98, at the request  
of the County Surveyor.

Fee #8  
File No. 19

Judith Wells  
County Recorder  
by Sue A. Deary  
Deputy

#### RECORD OF SURVEY for Rick Joy & Bill Pearson

Parcels 2 & 3 of 8 PM 32  
Being a portion of the SW 1/4 of Section 25  
T. 23 N., R. 14 E., M.D.M.

Plumas County ~ California  
Scale 1" = 100' October, 1995

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(916) 832-5571

SHEET 1 OF 1