

LEGEND


- FOUND 1/2" rebar with Plastic Cap RCE 11173 per (R1)
- SET 5/8" rebar with Aluminum Cap LS 2843
- Computed point
- └ Record point
- (R1) RECORD per 2 PM 1
- (R2) RECORD per 3 PM 68
- (M) Measured

BASIS OF BEARINGS

The Basis of Bearings for this map is the Northeasterly line of Parcel 1, shown as S28°44'06"E on 2 PM 1.

SURVEYOR'S STATEMENT

This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors' Act at the request of Eastern Plumas Hospital District in October, 1996.



John W. Hamby
John W. Hamby LS 2843

COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the Land Surveyors' Act this 29th day of JANUARY, 1998.



R. Tom Hunter
R. Tom Hunter RCE 30515
PLUMAS COUNTY SURVEYOR
License Expiration Date 3/31/00

RECORDER'S STATEMENT

Filed this 29th day of JANUARY, 1998 at 1:35 P.m. in Book 11 of Record of Surveys, at page 30, at the request of the County Surveyor.

Fee \$8.00
File No. 719

Judith Wells
County Recorder
by *Thomas P. Chard*
Deputy

RECORD OF SURVEY
for
Eastern Plumas Hospital District

Portion of Parcel 1, of 2 PM 1
Located in Section 1, T. 22 N., R. 13 E., M.D.M.
City of Portola, Plumas County, California
Scale 1"=100' September, 1996

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571