



Note: All bearings, distances and curve data shown are record per Gold Mountain Unit 5 "DANCING BEARS", 8 M 64, except those shown with (R3) which are measured per Lot Line Adjustment 229 O.R. 553

NOTE:  
This Record of Survey was prepared to reflect a Lot Line Adjustment for which a resolution is Recorded in Book 229 of Official Records at page 553.

**LEGEND**

- FOUND Rebar with Aluminum Cap LS 2843
- SET 5/8" Rebar & Aluminum Cap LS 2843
- Nothing Found or Set
- (R3) RECORD per 229 O.R. 553

Record of Survey  
for  
Gold Mountain Ranch, Inc.  
Lots 111 thru 116 & 118  
Unit 5 "Dancing Bears" 8 m 64  
A Portion of Section 15  
T. 22 N., R 13 E., M.D.M.  
Plumas County, California  
Scale 1" = 100' January, 1998

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571