

## Corner Notes

Monuments set by this survey were provided by the US Forest Service. They consist of a 5/8" aluminum rod with a 3 1/4" aluminum cap stamped as shown below.

Bearing trees and bearing objects were marked in accordance with USFS and BLM specification. Bearings and distances were measured to the apparent center of the trees, or to the X on the objects.

Where noted, non-Forest Service corners were monumented with a 5/8" rebar with 2" aluminum cap stamped BURGESS LAND SURVEYS LS 4790 and the corner information as shown below.

1 T23N R10E  
1 S30  
4 S31  
LS4790  
1992  
Found original 15"x11"x4" marked stone in small mound of stone and remains of original BTs:  
red fir stump bears N32°W 17.0' w/axe face, no marks  
red fir dead and rotted bears S56°W 40±, no marks  
Set USFS drive monument, rebuilt mound of stone and marked new BTs:  
14" white fir bears S74°W 8.9' marked 1/4S31 BT  
13" white fir bears N32°W 12.3' marked 1/4S30 BT

2 T23N R10E  
S30 S29  
S31 S32  
LS4790  
1992  
Found mound of stone and original BT:  
21" red fir bears N62°30'E 43.6', w/ scribing visible  
Set USFS drive monument, rebuilt mound of stone and marked new BTs:  
8" red fir bears S3°E 32.8' marked T23NR10ES32 BT  
24" red fir bears S69°W 22.5' marked T23NR10ES31 BT  
22" red fir bears N50°W 20.6' marked T23NR10ES30 BT  
16" red fir bears N74°E 26.4' marked T23NR10ES29 BT

3 T23N R10E  
1 S29  
4 S32  
LS4790  
1992  
Found original 11"x8"x6" marked stone and original BTs:  
52" ponderosa pine bears N27°E 38.3', w/ scribing visible  
34" ponderosa pine snag bears S35°30'E 35.6', no marks  
Set USFS drive monument, rebuilt mound of stone and marked new BT:  
9" red fir bears S35°E 12.7' marked 1/4S32 BT

4 N1/16  
S31 S32  
LS4790  
1992  
Set USFS drive monument, in a mound of stone and marked new BTs:  
12" white fir bears N33°E 89.9' marked N1/16S32 BT  
9" white fir bears N20°W 48.7' marked N1/16S31 BT

5 NW1/16 S32  
LS4790  
1992  
Set USFS drive monument, in a mound of stone and marked new BTs:  
11" white fir bears N44°45'W, 41.1' marked NW1/16S32 BT  
20" red fir bears N2°30'E 14.8' marked NW1/16S32 BT

6 T23N  
R9E R10E  
S36 S31  
LS5623  
1992  
Found a std. USFS drive monument in a mound of stone and BTs per 9 RS 110-111

7 E1/16  
C—C  
S31  
LS4790  
1992  
Set rebar with aluminum cap in a mound of stone

8 T23N R10E  
1/4  
S31 S32  
LS4790  
1992  
Found original 14"x8"x5" marked stone in mound of stone  
Set USFS drive monument, rebuilt mound of stone and marked new BTs:  
9" white fir bears S31°E 30.4' marked 1/4S32 BT  
15" white fir bears S39°30'W 44.7' marked 1/4S31 BT

9 W1/16  
C—C  
S32  
LS4790  
1992  
Set USFS drive monument, in a mound of stone and marked new accessories:  
18" white fir bears N57°45'E 13.8' marked CW1/16S32 BT  
5'x4'x3' granite boulder bears S64°30'E 21.6' marked BXO

10 C-S-SE  
1/64  
S31  
LS4790  
1992  
Set USFS drive monument, in a mound of stone and marked new BTs:  
19" white fir bears S85°E 298.1' marked CSSE1/64S31 BT  
29" red fir bears S39°45'E 179.1' marked CSSE1/64S31 BT

11 S-S 1/64  
S31 S32  
LS4790  
1992  
Set USFS drive monument, in a mound of stone and marked new BTs:  
10" white fir bears S7°E 11.7' marked SS1/64S32 BT  
31" red fir bears S84°W 12.8' marked SS1/64S31 BT

12 C-S-SW  
1/64  
S32  
LS4790  
1992  
Set USFS drive monument, in a mound of stone and marked new BTs:  
10" red fir bears S88°W 40.6' marked CSSW1/64S32 BT  
8" white fir bears S40°30'W 57.0' marked CSSW1/64S32 BT

13 T23N  
R9E R10E  
S36 S31  
S1 S6  
T22N  
LS4790  
1992  
Found mound of stone and original BTs:  
25" ponderosa pine bears N73°E 18.6', no marks  
49" Douglas fir bears S35°W 39.6', w/ healed blaze  
22" incense cedar bears N19°W 5.3', w/ healed blaze  
Set USFS drive monument, rebuilt mound of stone and marked new BT:  
14" ponderosa pine bears S28°E 28.0' marked T22NR10ES6 BT

14 T23N R10E  
1 S31  
4 S6  
T22N  
LS4790  
1992  
No original evidence found. At single proportion position set USFS drive monument, rebuilt mound of stone and marked new BT:  
64" incense cedar bears S34°W 22.2', marked 1/4S6 BT  
11" white fir bears S61°E 34.9', marked 1/4S6 BT

15 T23N R10E  
S31 S32  
S6 S5  
LS4790  
1992  
Found mound of stone and original BTs:  
44" red fir bears S69°W 44.8', w/ scribing found stumphole bears N22°W 55±, no marks  
Set USFS drive monument, rebuilt mound of stone and marked new BTs:  
20" red fir bears S35°W 43.9' marked T22NR10ES6 BT  
27" red fir bears N14°W 6.3' marked T23NR10ES31 BT  
17" white fir bears S38°E 43.9' marked T22NR10ES5 BT  
8" white fir bears N38°E 42.8' marked X BT

16 T23N R10E  
1 S32  
4 S5  
T22N  
LS4790  
1992  
Found mound of stone and original BT:  
26" red fir bears S47°E 25.1', verified by Joe Edgerton of the USFS in 1976  
Set USFS drive monument, rebuilt mound of stone and marked new BTs:  
16" red fir bears N60°E 13.1' marked 1/4S32 BT

17 T23N R10E  
S20 S21  
S29 S28  
LS4790  
1998  
Found original 14"x7"x6" marked stone and original BTs:  
16" red fir bears S79°30'W 9.2', w/ scribing visible  
Set Aluminum Capped Aluminum pipe. rebuilt stone mound and marked BTs:  
15" white fir, N88°E, 80.6' mkd T23NR10E S21 BT  
16" white fir, S44°30'E, 3.2 mkd T23NR10E S28 BT  
17" red fir, N28°W, 42.2 mkd T23NR10E S20 BT

18 T23N R10E  
S35 S36  
S2 S1  
LS5326  
1994  
Found USFS drive monument in a mound of stone and original BTs:  
34" Jeffrey pine snag bears S42°E 37.6' w/ open blaze  
40" incense cedar bears S59°30'W 36.0' w/ healed blaze  
40" Douglas fir bears N7°30'W 87.1' w/ healed blaze

## Record of Survey for

Shaffer-Ulch and USDA-Plumas National Forest

Sections 31 and 32 T23N R10E MDM  
in the unincorporated territory of Plumas County California

