

LEGEND

- FOUND Rebar with Aluminum Cap LS 2843
- FOUND Rebar with Plastic Cap LS 2843
- SET Rebar with Aluminum Cap LS 2843
- Nothing Found or Set
- (R1) RECORD per 8 M 41
- (R2) RECORD per 8 M 92
- (R3) RECORD per 8 M 96
- (R4) RECORD per 761 O.R. 733
- (R5) RECORD per 761 O.R. 740
- (R6) RECORD per 761 O.R. 751

SURVEYOR'S STATEMENT


This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyors' Act at the request of Dariel Garner, in December, 1998.



John W. Hamby LS 2843

COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the Land Surveyors' Act this 10th day of March, 1999.




R. Tom Hunter RCE 30515
 PLUMAS COUNTY SURVEYOR
 License Expiration Date 3/31/00

RECORDER'S STATEMENT

Filed this 10th day of March, 1999 at 1:30 P.m. in Book 11 of Record of Surveys, at page 13, at the request of the County Surveyor.

Fee #800
 File No. 1788

Judith Wells
 County Recorder
 by Thomas R. Crawford
 Deputy



RECORD OF SURVEY for Gold Mountain Ranch, Inc.

Lot 55, Unit 3 "FALLING WATER", 8 M 41
 Lot 174, Unit 8 "RED SKY", 8 M 92
 Lot 208, Unit 9, "GREAT SPIRIT", 8 M 96

A portion of Sections 16 & 17
 T. 22 N., R. 13 E., M.D.M.

Plumas County ~ California
 Scale 1" = 100' January, 1999

Hamby Surveying Inc.
 P.O. Box 1209
 Portola, CA 96122
 (530) 832-5571