


Note: all bearings, distances and curve data shown are record per Gold Mountain Unit 18, "GEMSTONE", 9 M 36, except those shown with (R1) which are measured per Lot Line Adjustment Document 2001-04488.



RECORD OF SURVEY
for
Gold Mountain Ranch, Inc.
Gold Mountain Subdivision

A portion of Section 15
T. 22 N., R. 13 E., M.D.M.

Plumas County ~ California
Scale 1" = 50' April, 2001

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571

LEGEND

- FOUND Rebar with Aluminum Cap LS 2843
- FOUND 5/8" Rebar with Plastic Cap LS 2843
- SET 5/8" Rebar with Aluminum Cap LS 2843
- Nothing found or set

(R1) Record per Document 2001-04488