

LEGEND


- FOUND Rebar with Aluminum Cap LS 2843
- FOUND 3/4" I.P. open, set tag LS 2843.
- ☒ FOUND 1/2" rebar with plastic cap, not readable
- SET 5/8" Rebar & Aluminum Cap LS 2843
- Found 5/8" Rebar & Plastic Cap LS 2843
- Nothing found or set

(R1) RECORD per 9 PM 8

(R2) RECORD per 8 RS 8

(R3) RECORD per 7 RS 149.


(R4) RECORD per Book A Maps page 32.



The Basis of Bearings for this map is the East line of Block 20, shown as S22°47'00"E on the map filed in the office of the Recorder of Plumas County in Book 9 Parcel Maps at page 8.

SURVEYOR'S STATEMENT

*This map correctly represents a survey made by me or under my direction
in conformance with the requirements of the Professional Land Surveyor's
Act at the request of Justin Williams in August, 2003.*



John W. Hamby
John W. Hamby LS 2843

COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the Professional Land Surveyor's Act this 3rd day of October, 2003.



2 Tom Winter

R. Tom Hunter RCE 30515
PLUMAS COUNTY SURVEYOR
License Expiration Date 3/31/04

RECORDER'S STATEMENT

Filed this 6th day of October, 2003 at 8:45 a.m. in
Book 13 of Record of Surveys, at page 5, at the request
of the County Surveyor.

Fee \$ 8.00
File No. 2003-12022

Kathleen Williams
County Recorder
by Jaye D.
Deputy

RECORD OF SURVEY
for
Justin Williams

A portion of Block 21, Northern Addition to Portola
Section 36

mas County ~ California
gle 1" = 50' August, 2003

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571