

<p>T22N R8E 1/4 S26 S35 LS 3621 1980</p> <p>CORNER No. 2</p> <p>FD. A STD. USFS ALUM. CAP IN A MOUND OF STONE. CORNER FALLS ON A MODERATE WEST SLOPE IN SCATTERED TIMBER AND BRUSH.</p> <p>FD. A 15" FIR, N74E, 10.3' -HB REC. A 10" FIR, N74E, 10.3' (1) FD. A RED FIR SNAG, S19E, 27.2' -HB REC. A 14" FIR, S19E, 27.2' (1)</p>	<p>S 1/16 S34 S35 LS 4753 2003</p> <p>CORNER No. 10</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A SMALL MOUND OF STONE. CORNER FALLS IN THE CENTER OF AN OLD SKID ROAD IN THICK MANZANITA.</p> <p>SCRIBED A 9" PONDEROSA PINE, N3 1/4W, 80.7' "S 1/16 S34 BT" SCRIBED AN 8" WHITE FIR, S53E, 87.8' "S 1/16 S35 BT"</p>	<p>CORNER NOTES</p> <p>STD USFS MON = 3 1/4" ALUM CAP ON A 2" ALUM PIPE HB = HEALED BLAZE VS = VISIBLE SCRIBING (1) = REC. PER 5 RS 143 (2) = REC. PER GLO (3) = REC. PER 4 RS 66</p>	<p>T21N R8E 1/4 S3 S10 LS 4753 2003</p> <p>CORNER No. 28</p> <p>FD. A 12 X 10 X 7 INCH STONE MKD "1/4" IN A MOUND OF STONE. SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD AND REBUILT MOUND. LAID STONE ALONGSIDE.</p> <p>FD. A 32" INCENSE CEDAR, S34E, 49.8' -HB REC. A 12" CEDAR, S35E, 75 LKS (2) SCRIBED A 13" INCENSE CEDAR, N64E, 5.9' "1/4 S3 BT" REC. 40" FIR, N12 1/2E, 66 LKS PER (2) NOT FOUND</p>
<p>N 1/16 C S35 LS 4753 2003</p> <p>CORNER No. 4</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A GENTLE WEST SLOPE.</p> <p>SCRIBED A 15" WHITE FIR, N81E, 4.8' "CN 1/16 S35 BT" SCRIBED A 10" RED FIR, S9E, 28.8' "CN 1/16 S35 BT"</p>	<p>SW 1/16 S35 LS 4753 2003</p> <p>CORNER No. 11</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE IN AN OLD SKID TRAIL AT THE EDGE OF A CLEAR CUT.</p> <p>SCRIBED A 7" WHITE FIR, N89E, 18.0' "SW 1/16 S35 BT" SCRIBED A 7" INCENSE CEDAR, N20W, 37.0' "SW 1/16 S35 BT"</p>	<p>N 1/16 S3 S2 LS 4753 2003</p> <p>CORNER No. 21</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE EAST SLOPE IN SCATTERED FIR AND CEDAR WITH LIGHT UNDERGROWTH.</p> <p>SCRIBED A 20" DOUGLAS FIR, N27E, 46.8' "N 1/16 S2 BT" SCRIBED AN 11" DOUGLAS FIR, S40W, 3.0' "N 1/16 S3 BT"</p>	<p>T21N R8E S3 S2 S10 S11 LS 4753 2003</p> <p>CORNER No. 29</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A MOUND OF STONE AT REC. FROM FD. BT. CORNER FALLS ON A STEEP EAST SLOPE, 80± EAST OF A ROAD.</p> <p>REC. 30" FIR, S32E, 50 LKS PER (2) NOT FOUND FD. A 60" WHITE FIR, N37E, 35.0' - CHOPPED OUT SCAR REC. 50" FIR, N37E, 53 LKS (35.0') (2)</p> <p>THE CHOPPING IS ABOUT 40 YEARS OLD BUT I FOUND A FLAT SURFACE ABOVE THE SCAR. I BELIEVE OTHERS LOOKED TOO DEEP FOR SCRIBING AND DESTROYED IT. I USED THIS TREE TO SET THE CORNER.</p> <p>SCRIBED A 14" DOUGLAS FIR, S25 1/2E, 29.8' "T21N R8E S11 BT" SCRIBED A 19" DOUGLAS FIR, N45 1/4W, 42.9' "T21N R8E S3 BT" SCRIBED A 29" DOUGLAS FIR, S56W, 22.4' "T21N R8E S10 BT"</p>
<p>T22N R8E 1/4 S34 S35 LS 3621 1980</p> <p>CORNER No. 5</p> <p>FD. A STD. USFS ALUM. CAP IN A MOUND OF STONE. CORNER FALLS ON A GENTLE WEST SLOPE IN HEAVY REGROWTH.</p> <p>FD. A DEAD AND DOWN RED FIR, N17E, 27.2' -VS REC. A 12" PINE, N17E, 27.2' (1) FD. AN 8" RED FIR SNAG, N48W, 30.7' -HB REC. A 7" PINE, N48W, 30.7' (1)</p>	<p>S 1/16 C S35 LS 4753 2003</p> <p>CORNER No. 12</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A SMALL MOUND OF STONE. CORNER FALLS ON A GENTLE SOUTHWEST SLOPE IN TIMBER AT THE EDGE OF A LOGGED AREA.</p> <p>SCRIBED A 7" WHITE FIR, S46E, 12.5' "CS 1/16 S35 BT" SCRIBED A 9" WHITE FIR, N83W, 32.7' "CS 1/16 S35 BT"</p>	<p>T21N R8E 1/4 S4 S3 LS 3621 1980</p> <p>CORNER No. 22</p> <p>FD. A STD USFS ALUM. MON. IN A MOUND OF STONE. CORNER FALLS ON A GENTLE WEST SLOPE IN TIMBER, 75± WEST OF A ROAD.</p> <p>FD. A 17" INCENSE CEDAR, N31W, 34.1' -HB NO RECORD OF BEARING TREE FD. A 22" WHITE FIR, S22E, 32.4' NO RECORD OF BEARING TREE REC. 16" FIR, N20W, 26 LKS PER (2) NOT FOUND REC. 20" FIR, S3E, 9 LKS PER (2) NOT FOUND</p>	<p>E 1/16 C-C S3 LS 4753 2003</p> <p>CORNER No. 23</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE EAST SLOPE IN AN OLD SKID ROAD IN SPARSE WHITE FIR AND INCENSE CEDAR.</p> <p>SCRIBED A 10" WHITE FIR, N56E, 21.1' "CE 1/16 S3 BT" SCRIBED A 14" WHITE FIR, N87W, 36.8' "CE 1/16 S3 BT"</p>
<p>W 1/16 C-C S35 LS 4753 2003</p> <p>CORNER No. 6</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A SMALL MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE IN TIMBER AND BRUSH.</p> <p>SCRIBED A 10" WHITE FIR, S36 1/4W, 46.1' "CN 1/16 S35 BT" SCRIBED AN 8" WHITE FIR, N51W, 7.8' "CN 1/16 S35 BT"</p>	<p>T22N R8E 1/4 S34 S3 T21N LS 4790 1980</p> <p>CORNER No. 15</p> <p>FD. A STD. USFS ALUM. CAP IN A MOUND OF STONE. CORNER FALLS ON A MODERATE WEST SLOPE IN HEAVY TIMBER AND BRUSH.</p> <p>FD. A 20" WHITE FIR, S66W, 19.2' -HB REC. A 9" FIR, S67W, 19.0' (1) FD. A 19" WHITE FIR, S33E, 7.7' -HB REC. AN 8" FIR, S30E, 7.5' (1)</p>	<p>T21N R8E 1/4 S3 S2 LS 4753 2003</p> <p>CORNER No. 24</p> <p>ORIGINAL 14 X 7 X 7 INCH STONE SEARCHED FOR, NOT FOUND. SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATELY STEEP EAST SLOPE IN THICK TIMBER.</p> <p>SCRIBED AN 8" WHITE FIR, S17E, 11.2' "1/4 S2 BT" SCRIBED A 9" WHITE FIR, N50W, 15.2' "1/4 S3 BT" REC. 5" OAK, S23W, 200 LKS PER (2) NOT FOUND</p>	<p>SE 1/16 S3 LS 4753 2003</p> <p>CORNER No. 25</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A SMALL MOUND OF STONE AT THE BASE OF A 20" WHITE FIR, CORNER FALLS ON A MODERATE NORTHEAST SLOPE IN HEAVY TIMBER.</p> <p>SCRIBED A 10" WHITE FIR, N42W, 28.3' "SE 1/16 S3 BT" SCRIBED A 6" WHITE FIR, S74E, 16.6' "X BT"</p>
<p>T22N R8E C 1/4 S35 LS 4753 2003</p> <p>CORNER No. 7</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A SMALL MOUND OF STONE. CORNER FALLS ON A MODERATE SOUTHEAST SLOPE IN SCATTERED TIMBER AND HEAVY BRUSH.</p> <p>SCRIBED A 12" WHITE FIR, N81 1/2E, 28.1' "C 1/4 S35 BT" SCRIBED AN 11" WHITE FIR, N30E, 38.5' "C 1/4 S35 BT"</p>	<p>T22N R8E S34 S35 S3 S2 T21N LS 3621 1980</p> <p>CORNER No. 16</p> <p>FD. A STD. USFS ALUM. CAP IN A MOUND OF STONE. CORNER FALLS ON A STEEP SOUTHWEST SLOPE IN HEAVY TIMBER.</p> <p>FD. AN 11" BLACK OAK, S40E, 2.2' -HB REC. A 9" OAK, S40E, 2.2' (1) FD. A 15" WHITE FIR, S77W, 40.4' -HB REC. A 6" FIR, S77W, 40.4' (1) FD. A 17" WHITE FIR STUMP, N6E, 12.5' REC. A 13" FIR, N6W, 12.5' (1) REC. A 36" PINE, N33E, 46.0' PER (3) NOT FOUND</p>	<p>S 1/16 S3 S2 LS 4753 2003</p> <p>CORNER No. 26</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A STEEP WEST SLOPE IN TIMBER AND BRUSH.</p> <p>SCRIBED A 10" WHITE FIR, S65W, 13.6' "S 1/16 S3 BT" SCRIBED A 12" WHITE FIR, S14E, 4.3' "S 1/16 S2 BT"</p>	<p>T22N R8E 1/4 S35 S36 LS 3621 1980</p> <p>CORNER No. 9</p> <p>FD. A STD. USFS ALUM. CAP IN A MOUND OF STONE. CORNER FALLS IN A FLAT AREA NORTHWEST OF AN OPEN LAVA REEF.</p> <p>FD. A 19" FIR SNAG, S55E, 29.4' -VS REC. A 15" FIR, S55E, 29.4' (1) FD. A 12" RED FIR, N32W, 19.5' -HB REC. A 7" FIR, N32W, 19.5' (1)</p>
<p>E 1/16 C-C S35 LS 4753 2003</p> <p>CORNER No. 8</p> <p>SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD IN A MOUND OF STONE. CORNER FALLS ON A MODERATE WEST SLOPE IN TIMBER AND BRUSH.</p> <p>SCRIBED A 16" WHITE FIR, N22E, 11.0' "CE 1/16 S35 BT" SCRIBED A 10" WHITE FIR, S42E, 19.8' "CE 1/16 S35 BT" S20W, 60' TO OLD CORNER</p>	<p>T22N R8E 1/4 S35 S2 T21N LS 4753 2003</p> <p>CORNER No. 17</p> <p>FD. A 20 X 12 X 4 INCH STONE MKD "1/4" IN A MOUND OF STONE. SET A 3 1/4" USFS ALUM. CAP ON A 5/8" ALUM. ROD AND REFRESHED MOUND. CORNER FALLS ON A STEEP WEST SLOPE IN BRUSH.</p> <p>FD. A 27" SUGAR PINE, S3E, 70.6' -VS IN A CHOPPED OUT FACE REC. A 7" SUGAR PINE, S3E, 107 LKS (2) SCRIBED AN 11" INCENSE CEDAR, N72E, 25.2' "1/4 S35 BT"</p>	<p>T21N R8E 1/4 S3 S2 LS 4753 2003</p> <p>CORNER No. 27</p> <p>SCRIBED A 10" WHITE FIR, S65W, 13.6' "S 1/16 S3 BT" SCRIBED A 12" WHITE FIR, S14E, 4.3' "S 1/16 S2 BT"</p>	<p>T22N R8E 1/4 S35 S36 LS 3621 1980</p> <p>CORNER No. 9</p> <p>FD. A STD. USFS ALUM. CAP IN A MOUND OF STONE. CORNER FALLS IN A FLAT AREA NORTHWEST OF AN OPEN LAVA REEF.</p> <p>FD. A 19" FIR SNAG, S55E, 29.4' -VS REC. A 15" FIR, S55E, 29.4' (1) FD. A 12" RED FIR, N32W, 19.5' -HB REC. A 7" FIR, N32W, 19.5' (1)</p>

RECORD OF SURVEY

FOR

USDA FOREST SERVICE
PLUMAS NATIONAL FOREST

"McNAIR"

IN SECTION 35, T 22 N, R 8 E,
AND SECTION 3, T 21 N, R 8 E, MDM IN
THE UNINCORPORATED AREA OF
PLUMAS COUNTY,
STATE OF CALIFORNIA

DEL TERRA INC.
SURVEYING
1168 INDUSTRIAL ST.
REDDING, CA 96002
PHONE (530) 241-8050

SCALE: NONE DATE: AUGUST, 2001
SHEET 2 OF 2