


NOTES

The Basis of Bearings for this map is the North line of the Southeast 1/4 of Section 8, shown as N88°51'51"W on the Record of Survey for Emery and Joan McRoberts, filed in the office of the Recorder of Plumas County in Book 11 Record of Surveys at page 113.

This Record of Survey was prepared to reflect a Lot Line Adjustment for which a resolution is Recorded as Document 2004-03256, Plumas County Records.




LEGEND

- FOUND 5/8" Rebar with Aluminum Cap LS 2843
- FOUND 1/2" rebar
- SET 5/8" Rebar & Aluminum Cap LS 2843
- (R1) RECORD per 11 RS 113
- (R2) RECORD per 4 M 97

02085

SURVEYOR'S STATEMENT


This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Professional Land Surveyor's Act at the request of Don Turk in October, 2003.



John W. Hamby
John W. Hamby LS 2843

COUNTY SURVEYOR'S STATEMENT

This map has been examined in accordance with Section 8766 of the Professional Land Surveyor's Act this 6th day of January, 2004



R. Tom Hunter
R. Tom Hunter RCE 30515
PLUMAS COUNTY SURVEYOR
License Expiration Date 3/31/04

RECORDER'S STATEMENT

Filed this 7th day of April, 2004 at 2:21 p.m. in Book 13 of Record of Surveys, at page 30, at the request of the County Surveyor.

Fee \$8.00
File No. 2004-03254

Kathleen Williams
County Recorder
by *Kathleen Williams*
Deputy

RECORD OF SURVEY
for
Don Turk

Lots 6, 8 & 9, 4 M 96
Plumas-Eureka Estates Unit No. 2
and

a portion of Section 8, T. 22 N., R. 12 E., M.D.M.
Plumas County ~ California
1" = 50' October, 2003

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571

Sheet 1 of 1